

2015 MITSUBISHI Lancer Evolution X GSR		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-CZ4A	DISPLACEMENT 1,998 cc		
YEAR / REG. 2015/03	MILEAGE 74,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Sedan		
CHASSIS NO. CZ4A-0801190	DIMENSIONS (L X W X H) 450 × 181 × 148 cm		
SALES POINTS			
Alloy Wheels Navigation System		Back Camera	
INSPECTOR REPORT			
Medium wear on driver's seat. Console A has damage (code &12073). Light scratches are present on the left rear door and left quarter panel. Damage (A2207, A present) is noted on the front bumper bottom and side spoiler bottom. The carpet shows wear (code &12073), and the floor mat has a medium burn. The front under cover is scuffed, and the front glass has damage (codes A2214, &2143, &2068).			

車種登録番号		セーラー		ドアクラス		3 4		ボディクラス		セダン		年式		9	
H27/		3月		三菱		ランサー E X		グレード		GSR HKSマフラーGTシフト ターボエロミラーHIDスマ		車検区分		2WD 2WD 4WD	
車種		自家用 ・ その他 ()		排気量		1998		型式		CBA-CZ4A		型式		A・B・C	
車検		- 年		月		日		燃料		ガソリン		ハイゼール		後付部品 (保証書 ・ 取扱説明書 等)	
発行		(旧所有者・新主人 (名) 姓 ・ 名 (姓) 名 (名))		車検		ハバブナド ()		シート		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日		車検		フロア		AT		()	
車検		- 年		月		日									