

2015 Mitsubishi Lancer Evolution X GSR X		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-CZ4A	DISPLACEMENT 1,998 cc		
YEAR / REG. 2015	MILEAGE 55,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Sedan		
CHASSIS NO. CZ4A-0801288	DIMENSIONS (L X W X H) 449 × 181 × 148 cm		
SALES POINTS			
Alloy Wheels Navigation System		Back Camera	
INSPECTOR REPORT			
Carrozzeria AR head-up display is installed but disconnected and unusable. Exterior has scrapes on the front bumper bottom, wheel scratches, and some other minor small scratches. Interior shows some age-related deterioration on the passenger seat and steering wheel leather.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27 / 一月	メーカー 三菱	ドア数 4	ボディ形状 セダン	評価点 4.5
車名 ランサー	グレード GSR X	期間区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1990 cc	型式 CBA-CZ4A	通称 AT	内装 A・B・C
車検 - - 年 月 / 日	燃料 ガソリン	変速機 AT	後日送付品 (保証書・取扱説明書 等)	
走行 55,000 km	カラーNo. ファントムブラックパール	エアコン QD・AAG・WAG ()	装備品のみ O印 を記入	
外装色 ()	内装色 ()	車検定員 人	PS	PW
ボディ 左・前・後	輸入 ディーラー	走行 12,800 km	エアバック	ABS
セールスポイント		TV		
検査記入欄		修復歴 有 (B)		
※カロッセツリア等、ABヘッドアップディスプレイが付いていますが装着し入れない状態です。		A サイズ W 輪廓 S サビ C 腐食 X 交換 XX 交換済		
・外装 ・フロントバンパー下塗り ・ホイールにガリキズ ・その他、細かい小さな傷はいくつか		B サイズ D キズ・ヘコ E 傷 F 傷 G ガラスキズ H 交換済		
・内装 ・前後シート、ステアリングの等部分に多少の経年劣化		C サイズ I 傷 J 傷 K 傷 L 傷 M 傷 N 傷 O 傷 P 傷 Q 傷 R 傷 S 傷 T 傷 U 傷 V 傷 W 傷 X 傷 Y 傷 Z 傷		
PW		シフト AT		
内装 シス		ヤブレ		
コグ		コグ穴		
オーディオ		オーディオ		
長さ 449 cm		幅 181 cm		
高さ 148 cm		最大積載量 kg		