

2015 MITSUBISHI Outlander 24G Navigation Package		OVERALL R	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-GF8W	DISPLACEMENT 2,359 cc		
YEAR / REG. 2015/07	MILEAGE 58,463 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. GF8W-0300668	DIMENSIONS (L X W X H) 466 × 180 × 168 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Adaptive Cruise Control Back Camera		Roof Rails Pre-Collision Braking Side Camera Navigation System	
INSPECTOR REPORT			
Core support bent, left and right side members bent, AC faulty, steering wheel worn, seat burn hole, studless tires, underbody rust, repairs done, front repair history.			

初年度登録	メーカー 三菱	ドア数 5	SUV/クロカン	駆動形式 後置		
H27 / 7月	車名 アウトランダー	グレード 2.4 Gナビッケージ	2WD 4WD ☒	R		
車種 自動車 ・ その他（ ）	排気量 2400 cc	型式 DBA-GF8W	運転方式 左ハンドル	内装 A・C・C		
年式 - - 年 月	納期 交付日 ハイブリッド ()	ディーゼル	検査受付品 (保証書・取扱説明書等)			
走行 [国にマチュウ登録した車両] * (中古車) * (新車) 十 万 千 百 十 マイル ☐ ☐ ☐ ☐ ☒ 5 8 . 4 6 3	シフト フロア AT					
外観色 クロ (X42)	カラーヘルメット AD・GLO・WAC・()	禁制品のみのO印を記入				
()	内装色 ブラック	標準定員 7人	サドルーフ	革シート		
左・右・両方	インター・運行	マイケルズ目録 11,100円	エアロック ABS	キーレス		
セールスポイント						
社外アルミ付き冬タイヤ						
検査記入欄						
コアシポートヒズミ、左右サイドメンバーヒズミ、AC不良、ハンドルスレ、シートコグ穴、スタッドレスト、下廻りサビ、補修、F修理歴						
FW	トランス	ワレ	小ギヤ	オイル		
内装	シート	サブ	コグ	コグ穴		
オートマチック						
車体番号 GF8W-0300668						
年月 日 家でどこまであるか						
最大積載量						