


2015 Subaru WRX STI STI		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-VAB	DISPLACEMENT 1,994 cc		
YEAR / REG. 2015/12	MILEAGE 70,509 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Sedan		
CHASSIS NO. VAB-010738	DIMENSIONS (L X W X H) 460 × 180 × 148 cm		
SALES POINTS			
Alloy Wheels Navigation System		Side Camera	
INSPECTOR REPORT			
Minor scratch on door mirror, right tail panel has bodywork/paint distortion.			

初年度登録		メーカー		ドア数		ボディ形状		駆動部		車種	
H27 / 12月		スバル		4		セダン				新車	
車名		WRX STI		グレード		STI		駆動区分		3.5	
								2WD			
								4WD			
車種		良車用・その他 ()		排気量		2000 CC		型式		CBA-VAB	
								運転形式		内装	
										A・B・C	
車検		8年12月		抜消		燃料		ディーゼル		検日選択 (保証書・取扱い明書等)	
						シフト		ハイブリッド ()			
走行		口内にマークを記入 (※交換・※盗品・※未検)		マイル		フロア 6 MT					
		70,000									
外装色		カラーNo		エンジン							
		ブラック (D4S)		AG・AGC・WAG・()						整備品のみ O印 を記入	
()		白車検 (1年内に「白車」を記入)		標準定員		5人					
ハテシ		左・右		輸入国		ディーラー		走行		12,500円・預託金	
										エブリック	
										AGC	
										AT	
										モータース	
セールスポイント											
CD/バックカメラ/TC機構滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/モロリーナビ他/フルセグTV/衝突安全ボディ/4WD /ターボ/エアロパーツ/DVD再生/ミュージックサーバー/ミュージックプレーヤー接続可/サイドカメラ											
検査記入欄											
ドアクラウ											
右テールパネルBP歪み											
修復歴											
有・無											
A	型式	U	ヘンロケル	B	型式/ヘンロ	P	色あせ/ボタ	G	ガラス/		
W	修理	S	サビ	C	腐食	X	交換	XX	交換		
登録No	月 日 までに名義である										
車体番号	VAB-010738										
FW	シボ	シボ	シボ	シボ	シボ	シボ	シボ	シボ	シボ	シボ	シボ
内装	シボ	シボ	シボ	シボ	シボ	シボ	シボ	シボ	シボ	シボ	シボ
車検	459	179	147	最大積載量							



修復歴									
有。()									
A	キズ	U	ヘコみ・スリ	B	キズ・ヘコミ	P	色あせ・ボケ	G	ガラス・スリ
W	腐蝕部	S	サビ	C	腐食	X	交換部	XX	交換済
登録No.									名義
									月 日 までに名義変更する
車体番号 VAB-010738									
シリアル No.									
車幅	長さ	459	幅	179	高さ	147	最大積載量		