

2015 Suzuki Alto Lapin 660 X		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-HE33S	DISPLACEMENT 658 cc		
YEAR / REG. 2015/11	MILEAGE 114,000 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Pink		
BODY TYPE Hatchback			
CHASSIS NO. HE33S-122409	DIMENSIONS (L X W X H) 340 × 148 × 153 cm		
SALES POINTS			
Alloy Wheels Front Camera		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Minor scratch on rear bumper			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/11月	メーカー スズキ	ドア枚数 5	ボディ形状 コンパクトハッチバック	駆動方式 2WD	グレード 660 X ツートンカラー/社外SDナビ/地デジTV/ETC/	4WD	年式 11	車種 アルトラパン	登録区分 4
車種 自家用・その他 ()	排気量 660	CC CC	型式 DBA-HE33S	通称 型式	内装 A・B・C	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書 等)	
車検 - 年 - 月 / 日	走行 114,000	マイル マイル	インパネ	CVT	エアコン	AG・AG・WAG・ ()	装備品のみ O印 を記入		
外装色 コフレックツバルボディホワイトパール	カラーNo. ()	内装色 ()	乗車定員 4 人	リサイクル料 7,950円	預託料 7,950円	エブリック	GS	GS	
セールスポイント キーレスエントリー/ABS/運転席エアバック/助手席エアバック/メモリーナビ他/ワンセグTV/衝突被害軽減ブレーキ/ETC/アイドリングストップ/スマートキー/盗難防止システム/HID・キセノン・ディスチャージ/横滑り防止装置 (ESC)/シートヒーター/ベンチシート/CD									
検査記入欄 リアバンパー小傷									
修復歴 有・無									
A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換品 XX 交換時 登録No. 月 日 までに名義できる方 車体番号 HE33S-122409 FW トビ石 傷A フレ 外装 小 A・U A・曲 A・フレ 内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ									