

| 2015 Suzuki Alto Lapin X                                                                                                                                |                        | OVERALL               |          |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-----------------------|----------|
|                                                                                                                                                         |                        | 4                     |          |
|                                                                                                                                                         |                        | EXTERIOR              | INTERIOR |
|                                                                                                                                                         |                        | -                     | -        |
| MODEL CODE                                                                                                                                              | DISPLACEMENT           |                       |          |
| HE33S                                                                                                                                                   | 658 cc                 |                       |          |
| YEAR / REG.                                                                                                                                             | MILEAGE                |                       |          |
| 2015/09                                                                                                                                                 | 49,413 km              |                       |          |
| DOORS                                                                                                                                                   | SEATS                  |                       |          |
| 5                                                                                                                                                       | 4                      |                       |          |
| TRANSMISSION                                                                                                                                            | FUEL                   |                       |          |
| AT                                                                                                                                                      | Petrol                 |                       |          |
| STEERING                                                                                                                                                | EXTERIOR COLOR         |                       |          |
| Right                                                                                                                                                   | Other                  |                       |          |
| BODY TYPE                                                                                                                                               |                        |                       |          |
| Kei                                                                                                                                                     |                        |                       |          |
| CHASSIS NO.                                                                                                                                             | DIMENSIONS (L X W X H) |                       |          |
| HE33S-114879                                                                                                                                            | 340 × 148 × 153 cm     |                       |          |
| SALES POINTS                                                                                                                                            |                        |                       |          |
| Alloy Wheels                                                                                                                                            |                        | Pre-Collision Braking |          |
| Front Camera                                                                                                                                            |                        | Back Camera           |          |
| 360° Camera                                                                                                                                             |                        | Navigation System     |          |
| INSPECTOR REPORT                                                                                                                                        |                        |                       |          |
| Exterior: There are noticeable scratches and dents. Interior: There are some noticeable stains in parts. Repair history: No abnormalities in the frame. |                        |                       |          |

[illegible]