

2015 Suzuki Alto Lapin X		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HE33S	DISPLACEMENT 658 cc		
YEAR / REG. 2015/09	MILEAGE 55,734 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Brown		
BODY TYPE Kei			
CHASSIS NO. HE33S-116181	DIMENSIONS (L X W X H) 340 × 148 × 153 cm		
SALES POINTS			
Alloy Wheels Front Camera Back Camera Navigation System		Pre-Collision Braking Side Camera 360° Camera	
INSPECTOR REPORT			
JAAA certified. Left mirror: cracks, breaks. Shift knob: scuffs, scratches. Other trim: wrinkles, scuffs, scratches. Steering wheel: scuffs. Driver's seat: minor scuffs/wrinkles. Left front wheel: scrapes.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H27 / 9月	メーカー スズキ	ドア数 5	ボディ形状 軽四	評価点 4.5
車名 アルトラパン X	グレード X	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 660 cc	型式 HE33S	登録式 (A)・B・C	
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	後日進品 (色傷・取付部品等)	
走行 55,734 km	フロア	AT		
外装色 アーバンブ라운パールメタリック	カラーNo.	エアコン AG・AC・WAG ()	装備品のみ・O印を記入	
内装色 ()	乗車定員 4人		サンルーフ	革シート
左・前 左・前 左・前	ディーラー 直付	7,950円	エレクトロ	その他
セールスポイント				
CD/フルフラット/バックカメラ/横滑り防止装置 (ESC) / H I D ・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キースエントリー/ABS/助手席エアバック/メモリーナビ/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/シートヒーター/ベンチシート/DVD再生/全周囲カメラ/フロントカメラ/サイドカメラ				
検査記入欄				
JAAA鑑定 左ミラー、ヒビ、割れ、シフトノブ、スレ、キズ。他トリム、シワ、スレ、キズ ハンドル擦れ 僅、D席シワ擦れ小 左Fホイール割れ				
名義中				
月 日				
車検番号 HE33S-116181				
FR	トボ石	傷A	フレ	外装
内装	ヨゴレ	シミ	ヤブレ	コゲ
小	小	小	小	小
オイル	オイル	オイル	オイル	オイル
エアロ	エアロ	エアロ	エアロ	エアロ
シフト	シフト	シフト	シフト	シフト
車検	車検	車検	車検	車検
長さ	長さ	長さ	長さ	長さ
幅	幅	幅	幅	幅
高さ	高さ	高さ	高さ	高さ
重量	重量	重量	重量	重量