

2015 Suzuki Alto Lapin X		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-HE33S	DISPLACEMENT 658 cc		
YEAR / REG. 2015/08	MILEAGE 92,009 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pink	BODY TYPE Kei		
CHASSIS NO. HE33S-112325	DIMENSIONS (L X W X H) 340 × 148 × 153 cm		
SALES POINTS			
Alloy Wheels Front Camera 360° Camera		Pre-Collision Braking Back Camera Navigation System	
INSPECTOR REPORT			
Body line A. Disc read error. Left rear side member pre-bent. End panel dent.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/8月	メーカー スズキ	ドア数 5	ボディ形状 軽四	評価点 4
車名 アルトラパン	グレード X 純正ナビ・フルセグ・全周 カメラ・レーダー・キー	駆動方式 4WD	4WD	
車種 自家用・その他 ()	排気量 660 cc	型式 DBA-HE33S	通称 軽四	内装 A・B・C
年 -	月 -	日 -	燃料 ハイブリッド ()	ディーゼル
走行 92,009 km	インパネ	CVT	後日取り込み (保証書・取扱説明書 等)	
外装色 ピンク	カラーNo. (ZWA)	AG・BG・WAG・ ()	新車品のみ O印 を記入	
内装色 ()	乗車定員 4 人	ドアロック	サンルーフ	車シート
左・右 左・右	ディーラー 左・右	走行 7,950 km	エンジン	エアコン
セールスポイント				
フルフラットバックカメラ/ETC/横滑り防止装置 (ESC) /HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/メモリーナビ/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/シートヒーター/ベンチシート/全周カメラ/フロントカメラ/サイドカメラ				
検査記入欄				
ボディ線Aあり ディスク読み込み不良 左Rサイドメンバー先垂 エンドパネルU				
修理履歴				
有・無				
A ボディ U ヘッドライト B キズ・ヘコ P 衝突被害軽減 X 交換済 XX 交換済				
W 修理済 S サイズ C 腐食				
登録No. 月 日 まで(名義変更可能)				
車体番号 HE33S-112325				
シリアルNo.				
内装 トヨタ シェ ヤブレ コグ コグ穴 オーディオ スレ				
長さ cm 幅 cm 高さ cm 最大積載量 kg				