


2015 Suzuki Alto Van Van 660 VP		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HBD-HA36V		DISPLACEMENT 658 cc	
YEAR / REG. 2015/01		MILEAGE 15,000 km	
DOORS 5		SEATS 4	
TRANSMISSION MT		FUEL Petrol	
STEERING Right		EXTERIOR COLOR White	
BODY TYPE Hatchback			
CHASSIS NO. HA36V-101408		DIMENSIONS (L X W X H) 340 × 148 × 148 cm	
INSPECTOR REPORT			
Interior dirty, underbody rust, small scratches and dents on right front side panel, seat wear and scuffs.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/		メーカー スズキ		ドア枚数 5		ボディ形状 コンパクト/ハッチバック		評価点 R	
1月		車名 アルト		グレード バン 660 VP マ ニュアル5速車		駆動区分 2WD 4WD			
車歴 自家用・その他 ()		排気量 660		型式 HBD-HA36V		通称 型式		内装 A・B・C	
車検 9年1月 / 抹消		燃料 ガソリン		ディーゼル		後日送り品 (保証書・取扱説明書 等)			
走行 15,000マイル		シフト ハイブリッド ()							
外装色 スベリアホワイト		カラーNo. ()		エアコン A・B・AAG・WAG ()		整備品のみ O印 を記入			
()		内装色 色指定はO印に 「色番」と記入		乗車定員 4人		P3 PW AW サンルーフ 革シート			
ハンド 左・右		輸入 区分		ディーラー 並行		リサイクル料 7,410円・預託無		エディック ABS ナビ TV スピー	
セールスポイント キーレスエントリー/運転席エアバック/助手席エアバック									
検査記入欄 ルーム内汚れ 下廻りサビ 右Fサイドパネル廻り 小キズ有へこみ有 シートへたりスレ									
									
修復歴 0. 無									
A キズ U ヘコみ・凹み B キズ・ヘコみ P 色あせ・剥き G ガラスキズ W 補修跡 S サビ C 腐食 X 交換箇所 XX 交換所									
登録No. 月 日 まで(に)名義できる方 名義中									
車体 番号 HA36V-101408									
シリアル No.									
PW トボ石 傷A フレ 外装 小 A・U ホイル A・曲 エアロ 内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ 長さ 幅 高さ 最大積載量 Kg									