

2015 Suzuki Escudo 5D Land Breeze		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
TDA4W	2,393 cc		
YEAR / REG.	MILEAGE		
2015/09	98,684 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
TDA4W-291297	430 × 181 × 170 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Roof Rails		Cruise Control	
Navigation System			
INSPECTOR REPORT			
Repaired history: A/F inner UW, left front pillar U (small), left center pillar UW. Door power window switch faulty. Mirror has scratches. Driver's seat sagging (medium). Small scratches on door trim, pillar trim, cargo area trim, steering wheel, and console. Medium scratch on glove box. Traces of side repair and simple exterior paint repair. Exterior has fine scratches. Front glass has a medium stone chip. Headlights are hazy. Left fender stay has a wave/dent. Right side has small scratches and a small dent.			

[illegible]