

2015 Suzuki Every Van Join High Roof		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HBD-DA17V		DISPLACEMENT 658 cc	
YEAR / REG. 2015/04		MILEAGE 221,113 km	
DOORS 5		SEATS 4	
TRANSMISSION AT		FUEL Petrol	
STEERING Right		EXTERIOR COLOR White	
BODY TYPE Kei			
CHASSIS NO. DA17V-112225		DIMENSIONS (L X W X H) 340 × 148 × 190 cm	
INSPECTOR REPORT			
Left front bumper and fender misalignment. Tear/hole on the back of the passenger seat. Scratches and rust in several places overall. Steering wheel peeling. Damage to the left front inner panel, left front side member, and dashboard panel.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/4月		メーカー スズキ		ドア枚数 5		ボディー形状 軽四		評価点 R																																									
車名 エブリイ		グレード ジョインハイルー		駆動方式 2WD		4WD																																											
車歴 自家用・その他 ()		排気量 660 CC		型式 HBD-DA17V		通称 型式		A・B・C																																									
車検 9年4月 / 抹消		燃料 ガソリン		ディーゼル		後日選り品 (保証書・取扱説明書 等)																																											
走行 221,113 km		インパネ		AT																																													
外装色 ホワイト		カラーNo. ()		エアコン		新車定員 人																																											
ハンド 左・右		輸入 区分		ディーラー・並行		リース料 8,400円・税込		オプション AW サンルーフ 革シート																																									
セールスポイント AGS車 パワーウィンドウ		検査記入欄 左Fバンパー、フェンダーズレ有 助手席シート裏側破れ穴 全体的に数か所傷跡有 ハンドル剥がれ有り 左フロントインサイドパネル損傷 左フロントサイドメンバー損傷 ダッシュパネル損傷																																															
修復歴 無		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/へこみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> <tr> <td>登録No.</td><td colspan="8">月 日 までに名変できる方</td><td>名変中</td> </tr> <tr> <td>車体番号</td><td colspan="8">DA17V-112225</td><td></td> </tr> </table>								A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済	登録No.	月 日 までに名変できる方								名変中	車体番号	DA17V-112225								
A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ																																								
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																																								
登録No.	月 日 までに名変できる方								名変中																																								
車体番号	DA17V-112225																																																
FW トビ		備A		フレ		外装		小・中																																									
内装		ヨコ		シタ		ヤブ		コガ																																									
						コガ穴		オーディ穴																																									
長さ		幅		高さ		最大積載量		Kg																																									