

2015 Suzuki Hustler X		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
MR41S	658 cc		
YEAR / REG.	MILEAGE		
2015/07	40,000 km		
DOORS	SEATS		
5	4		
TRANSMISSION	FUEL		
AT	Hybrid (Petrol)		
STEERING	EXTERIOR COLOR		
Right	Red		
BODY TYPE			
Kei			
CHASSIS NO.	DIMENSIONS (L X W X H)		
MR41S-119653	340 × 148 × 167 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Back Camera		Navigation System	
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, exterior minor and light scratches, AA rating 4 points, steering wheel wear.			

車種		H27 / 7月		スズキ ハスラー		グレード X		ボディ形状 軽四		登録区分 2WD 4WD		新価点 4																																											
用途・その他 ()		請求書番号 660 CC		型式 MR4T5		通称名		内装 A・G・C																																															
乗換 -年-月-		販売店 インディーディーゼル		ハイブリッド ()		後日送付品 (保証書・取扱説明書等)																																																	
走行 40,000 km		インパネ AT																																																					
外装色 フェニックスレッドパール I カラーNo.		(A) AAG・WAG・()		装備品のみの O印 を記入																																																			
() (内装色) (内装色) 塗装変更		4人		サドルーフ 寒シート																																																			
シロ左・右 輸入国別 ディーゼラー 運行		リサイクル料 8,400円		エアクリーナー アブソーバ グループ TV キット																																																			
セールスポイント																																																							
ワンオーナーCD/DバックカメラETC横滑り防止装置 (ESC)/HID・キセノン・ディスチャージ運転席エアバック/スマートキー/キレレスエントリー/ABS/助手席エアバック/メモリーナビ付/ホンセイグTV/衝突被害軽減ブレーキ/Aイドリングストップ/シートヒーター/パンチシート																																																							
検査記入欄																																																							
内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価6点以上入れ ハンドルハゲ																																																							
<table border="1"> <thead> <tr> <th>A</th><th>KZ</th><th>H</th><th>S</th><th>C</th><th>D</th><th>X</th><th>F</th><th>G</th><th>Z</th><th>N</th><th>J</th><th>M</th><th>P</th></tr> </thead> <tbody> <tr> <td>無傷</td><td>軽微な傷</td><td>中程度の傷</td><td>大程度の傷</td><td>腐食</td><td>変形</td><td>穴開き</td><td>ガラス割れ</td><td>ドア破損</td><td>エンジンオイル漏れ</td><td>冷却水漏れ</td><td>油圧油漏れ</td><td>ブレーキ油漏れ</td><td>バッテリー液漏れ</td></tr> <tr> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table> 車体番号 MR4T5-119653														A	KZ	H	S	C	D	X	F	G	Z	N	J	M	P	無傷	軽微な傷	中程度の傷	大程度の傷	腐食	変形	穴開き	ガラス割れ	ドア破損	エンジンオイル漏れ	冷却水漏れ	油圧油漏れ	ブレーキ油漏れ	バッテリー液漏れ														
A	KZ	H	S	C	D	X	F	G	Z	N	J	M	P																																										
無傷	軽微な傷	中程度の傷	大程度の傷	腐食	変形	穴開き	ガラス割れ	ドア破損	エンジンオイル漏れ	冷却水漏れ	油圧油漏れ	ブレーキ油漏れ	バッテリー液漏れ																																										