

2015 Toyota Regiusace Van DX 4WD		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE LDF-KDH206V	DISPLACEMENT 2,982 cc		
YEAR / REG. 2015/07	MILEAGE 177,594 km		
DOORS 5	SEATS 3		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Minivan		
CHASSIS NO. KDH206-6010992	DIMENSIONS (L X W X H) 469 × 169 × 198 cm		
INSPECTOR REPORT			
Rear panel dent, multiple dents on the roof, cargo area has fading and a dent, partial rust on the undercarriage.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/		メーカー トヨタ		ドア枚数 5		ボディ形状 バン		評価点 3.5																					
7月		車名 レジアスエースバン		グレード DX 4WD		駆動区分 2WD 4WD																							
車歴 自家用・その他()	排気量 2980	型式 LDF-KDH206V	通称 型式	内装 A・B・C																									
車検 9年7月	抹消	燃料 ガソリン	デレゼル	後日送り品 (保証書・取付説明書 等)																									
走行 1万7千594マイル	インパネ	AT	記録簿、5キー2個																										
外装色 シルバー	カラーNo. (1E7)	エアコン	新備品のみ O印 を記入																										
()	内装色	乗車定員 3人	PS	PS	AW	サンルーフ	革シート																						
ハンド 左・右	輸入 区分	ディーラー	並行	リサイクル料	9,550円	預託金	エディック	ABS	ナビ																				
セールスポイント																													
ワンオーナー アウトサイドモール 寒冷地仕様 電格ミラー Rヒーター キーレス ドラレコ スタッドレスタイヤ積込			修復歴 有 (5)																										
検査記入欄			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ・凹み</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あせ・剥落</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>							A	キズ	U	ヘコミ・凹み	B	キズ・ヘコミ	P	色あせ・剥落	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコミ・凹み	B	キズ・ヘコミ	P	色あせ・剥落	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																				
RパネルU ルーフU多 荷室AU 下回り一部S			登録No. 名義中 月 日 までに名義できる方 車体 番号 KDH206-6010992 シリアル No. 																										
PW	トビ石	傷A	フレ	外装	小 (A)・(G)	ホイール A・曲	エアロ A・フレ	シリアル No.																					
内装	ヨコリ	シミ	ヤブレ	コゲ	コゲ穴	オーディ穴	スリ	長さ 469 cm	幅 169 cm																				
								高さ 198 cm	最大積載量 1000 Kg																				