


2015 SUBARU WRX STI STI 2.0 4WD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-VAB	DISPLACEMENT 1,994 cc		
YEAR / REG. 2015/01	MILEAGE 93,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Sedan		
CHASSIS NO. VAB-004596	DIMENSIONS (L X W X H) 460 × 180 × 148 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Duct part has P-grade peeling. Seat has wear, sagging, and wrinkles.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/1月	メーカー スバル	ドア枚数 4	ボディ形状 セダン	評価点 4																				
車名 WRX S4	グレード STI 2.0 4WD ボディ同色大型リアスポイラー	駆動区分 2WD 4WD																						
車種 自家用・その他 ()	排気量 2000 cc	型式 CBA-VAB	通称 型式	内装 A・⑨・C																				
車検 10年2月	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)																					
走行 93,000 km	シフト フロア 6 MT																							
外装色 WRブルー・パール	カラーNo. ()	エアコン ()	新車品のみ O印 を記入																					
内装色 ()	乗車定員 5人	⑤	サンルーフ	革シート																				
ハンド 左・()	輸入 区分	ディーラー	並行	12,500円・預託金																				
セールスポイント キーレスエントリー/A B S/運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/HDDナビ/フルセグTV/4WD/ETC/スマートキー/盗難防止システム/横滑り防止装置 (ESC)																								
検査記入欄 ダクト部分Pハゲあり シートスレヘタリシワ		修復歴 有・⑨																						
		<table><tr><td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td></tr><tr><td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換席</td><td>XX</td><td>交換席</td></tr></table>			A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換席	XX	交換席
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換席	XX	交換席															
		登録No. 月 日 までに名変更できる方																						
		車検 番号 VAB-004596																						
FW トビ石		備A	ワレ	外装 小 A・U A・曲 A・ワレ	エアロ No.	シリアル No.																		
内装 ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	長さ cm	幅 cm	高さ cm	最大積重量 kg														