

2016 BMW BMW X1 sDrive18i		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-HS15	1,498 cc		
YEAR / REG.	MILEAGE		
2016/08	30,591 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Station Wagon		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBAHS120905F02024	446 × 182 × 161 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Pre-Collision Braking		Back Camera	
Navigation System			
INSPECTOR REPORT			
Headlights fogged, no spare tire, minor scuffs in cargo area, steering wheel wear, seat wear, exterior stains.			

年式登録	メーカー	BMW	ドア数	5	ボディタイプ	ステーションワゴン	評価点																				
H28 / 8月	車名	X 1	グレード	s Drive 18 i	駆動方式	2WD 4WD	4																				
車種	自家用・その他()	排気量	1500 CC	型式	DBA-HS 15	運転形式	内装 A・B C																				
車検	9年8月 / 残月	燃料	ガソリン	チーゼル	登録年月日	()																					
走行	CIDにマーク記入(※全欄) * (※左半 ※ 右半)	シフト	ハバリアド ()	エンジン	自動変速品 ()	取扱い明書等																					
外観色	ブルー	カラーNo.	()	フロア	AT																						
()	内装色	黒革実質	5人	()	AAC・WAC・()																						
左・()	輸入区分	デュー	銀行	サイズ別	20,540円	国別税																					
セールスポイント																											
検査記入欄																											
ヘッドライトもり、スベアタイヤレス、荷室スレ小、ハンドルスレ、シートスレ、外装シミ																											
 修復歴 有 ()																											
<table border="1"> <thead> <tr> <th>A</th> <th>ボディ</th> <th>U</th> <th>ヘッドランプ</th> <th>B</th> <th>キズ・ヘコ</th> <th>P</th> <th>色あせ・汚れ</th> <th>G</th> <th>ガラスキズ</th> </tr> </thead> <tbody> <tr> <td>W</td> <td>輪郭部</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> </tbody> </table> 登録No. 月 日 家で名度でできる 車体番号 WBAHS 120905F 02024								A	ボディ	U	ヘッドランプ	B	キズ・ヘコ	P	色あせ・汚れ	G	ガラスキズ	W	輪郭部	S	サビ	C	腐食	X	交換済	XX	交換済
A	ボディ	U	ヘッドランプ	B	キズ・ヘコ	P	色あせ・汚れ	G	ガラスキズ																		
W	輪郭部	S	サビ	C	腐食	X	交換済	XX	交換済																		
FW	()	フレ	外装	小	カイル	エアロ	シリアル No.																				
内装	シート	シタ	ヤブル	コダ	コダク	オーディオ	オーディオ	オーディオ	オーディオ																		