

2016 BMW_Mini BMW Mini 3HB John Cooper Works		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-XMJCW	1,998 cc		
YEAR / REG.	MILEAGE		
2016/04	110,500 km		
DOORS	SEATS		
3	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Orange	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WMWXM920502D05079	387 × 173 × 141 cm		
SALES POINTS			
Alloy Wheels		Cruise Control	
Navigation System			
INSPECTOR REPORT			
Roof wrapping scratches, vehicle start-up warning light on, passenger side door mirror scratches.			

初年度登録		メーカー	MINI		ドア枚数	3	ボディ形状	コンパクトハッチバック	評価点	4
H28 /		車名	MINI		グレード	ジョンクーパーワークス			駆動区分	2WD 4WD
	4月	年次	2000	CC	型式	DBA-XMJ CW			通称形式	A・B・C
車種	良車用・その他()				排気量				内装	
車検	2	9	年	4	月	抹消	燃料	ガソリン	ディーゼル	後日返却品 (登録済・取付済等)
走行	口内にマークを記入(A:交換 ●:点検 ☆:劣化)	シフト	ハイブリッド	()	マイル	フロア 6 AT			スペアキー	
外観色	オレンジJ I		カラーNo.	Eアエロン	AG・QG・WAG・()	装備品のみの印を記入				
()	()		内装色	標準定員	4人	Fg	Pg	AM	サンルーフ	革シート
ハンドル	左・右	入庫区分	デ	直行	リサイクル料	エアバッグ	ABS	Gx	TV	モーター
17,700円 + 預託金										
セールスポイント										
・ルーフラグレーションラッピング ・純正ナビ ・パドルシフト ・ドライビングモード ・ヘッドアップディスプレイ ・令和8年4月エンジンマウント交換(記録無し)										
検査記入欄										
ルーフラッピングキズ 車両動き出し注意灯 助手席側ドアミラーキズ										
修復歴 有。(●)										
A	文字	U	へレスヤレ	B	文字へレス	P	他色セボテ	G	ガラスキ	
W	修理部	S	サビ	C	腐食	X	交換済	XX	交換済	
登録地		堺		300		表		6595		名義
月 日 までは名義である										
車体番号 WMMWXM920502D05079										
FW	トピ石	備A	フレ	外装	小	ホイール	エアロ	シリアル	No.	
内装	ヨゴレ	シミ	ヤブレ	コゲ	コガタ	オーディオス	スレ	車輪	径3	最大積重量
387mm		177mm		143mm						