

2016 BMW_Mini BMW Mini Clubman Cooper D Clubman		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LR20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2016/09	MILEAGE 77,300 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. WMWLR920702E72754	DIMENSIONS (L X W X H) 427 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels Back Camera		Sunroof Navigation System	
INSPECTOR REPORT			
Minor scratches, minor dents, minor scratches on wheels.			

初年度登録		メーカー		ドア数枚		ボディ形状		駆動方式		グレード		年価点	
H28 / 9月		MINI		5		コンパクトハッチバック						9.5	
		車名 MINI		型式 DBA-LR20		クラス クーバーDクラブマン		駆動区分 2WD 4WD					
車種 良用途・その他()		排気量 1990 CC		型式 CC		運転形式		内装		A・B・C			
車検 - - 年 / - 月 / - 日		燃料 ガソリン		ギヤ デカトル		後日送り品 (緑書置・取付書置等)							
走行 口内にマークを記入(※交換・※盗品 ※ 変更)		シフト ハイブリッド											
外装色 ペッパー ホワイト		カラーNo. ()		エンジン AG・QG・WAG・()		装備品のみの印記を記入							
()		自賠保(注)内に「盗難」を記入		標準定員 人		Fg		Pw		AM		サンルーフ	
ハサリ 左・右		出入 デ		行		19,440円・預託金		エフク		AB		TV	
セールスポイント													
★純正ナビ★純正17インチアルミ★クルコン★アイドリングストップ★スマートキー★プッシュスタート★観音開き★ツートンルーフ★ミラー一体型ETC★Bluetooth★MT・SPモード付★オートライト★スベアキー★													
検査記入欄													
小傷・小凹													
ホイル小傷													
修復歴													
有・無													
A	劣化	U	ヘコみやレキ	B	劣化・ヘコみ	P	熱変形・ボロボロ	G	ガラスの割れ				
W	修理痕	S	錆び	C	腐食	X	交換済	XX	交換済				
登録地													
月													
日													
車体番号													
WMWL R 920702 E 72754													
FW	トビ石	傷A	フレ	外装	小	ホイール	エアロ	シリアル	No.				
					A・U	A・曲	A・フレ						
内装	ヨゴレ	シミ	ヤブレ	コゲ	コガタ	オーディオ	ズレ	車庫	傷	傷	傷	傷	傷