

2016 BMW_Mini BMW Mini Crossover Cooper SD Crossover		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ZB20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2016/05	MILEAGE 73,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. WMWZB72090WU15741	DIMENSIONS (L X W X H) 412 × 179 × 155 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Navigation System			
INSPECTOR REPORT			
Interior dirt, small scratches, wheel scratches, seat scuffs, steering wheel scuffs			

ORIGINAL JAPANESE AUCTION SHEET

出品票		登録証番号	17840	無償取引番号	0001	シリアル番号		評価点	
前年度登録	車名	タイプ	グレード	駆動	4WD	5速	4.5		
H28	ミニクロスオーバー	5	クーパー SD	5	5	5			
5	型式 LDA-ZB20	排気量	2000 cc	燃料	ガソリン	5速			
車種	抹消済み	車種	自家用	シフト	AT	冷却	AAC	純正装備品	○をつける
走行距離	7 3 0 0 0	マイル	(交換)	(改ざん)	(不明)	純正ナビ	革シート	SR	
外装色	ブラックⅡ	色替(元色)	色替無	カラーNo.	内装色	TV種類(社外品含む)	○をつける		
車台No.	WMWZB72090WU15741			ナビ種類(社外品含む)	○をつける	CD	ワンセグ	アナログ	
登録No.		リサイクル	17,490	内装色	未確認	HDD	DVD	CD	
定員	5	乗員数	5	長さ	cm	DVD再生可			
輸入車のみ	モデル	型式	輸入区分	○	車種	左	○	○	
ストラーダナビ・フルセグTV・バックカメラ・BT・キセノン・LEDフォグ・17A W・パドルシフト・ETC・プッシュスタート・キーレス・ディーゼルトーボ									
注意事項・不具合箇所									
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入									
ルーム内汚れ									
小キズ									
ホイールキズ									
シートスレ									
ハンドルスレ									
フロント									
左									
右									
リア									
左									
右									
フロント									
左									
右									
リア									
左									
右									