

2016 Daihatsu COPEN Copen 660 Cero S		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LA400K	DISPLACEMENT 658 cc		
YEAR / REG. 2016/09	MILEAGE 54,146 km		
DOORS 2	SEATS 2		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Kei		
CHASSIS NO. LA400K-0018419	DIMENSIONS (L X W X H) 339 × 147 × 128 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Wheel scratches, door mirror scratches, minor exterior scratches (A) and dents (U), exterior repair marks, interior dirt. Front windshield has scratches, stone chips, cracks, and repair marks, replacement recommended. Interior has scratches, dirt, burns, holes, scuffs, and tears.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成28年 9月	車名・グレード コペン ゼロS	2WD 4WD	評価点 (4.5)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-LA400K	排気量 660 CC	ドア 2 形状 CP
定員 2人	積載 kg	外装 B	内装 B

車種 自家用	シフト FAT	セールスポイント (正常に機能するものに限ります)
車検 令和9年 10月 (日)	冷房 ナシ	スマートキー・ETC
走行 5万4千146 km	燃料 ガソリン	SDナビ フルセグTV バックカメラ
色 レッド2	色コード R70/FM51	

R券 8,640 円	装備品 (純正品に限り○をつけてください)
注意事項申告欄	(PS) (PW) (BS) (TB) (AW) SR ナビ TV カフ
ホイール キズ	新車保証書 有・無
ドアミラー キズ	
外装 小A・小U	
外装補修跡	
ナイスウヨゴレ	
フロントガラス 内装 キズ・傷・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・キレ・破レ	
車台番号 0018419	
登録番号 葛飾 580 い 5170	

A-キズ E-エケボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
型式指定番号 17752	類別区分番号 0004
車検有効期限 339 日	長さ 147 cm
	高さ 128 cm