


2016 Honda N-BOX GL Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JF1	DISPLACEMENT 658 cc		
YEAR / REG. 2016/08	MILEAGE 14,986 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Kei		
CHASSIS NO. JF1-1870113	DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
Core support rust hole, dashboard adhesive marks, interior scratches, wheel center cap scratches, underbody rust paint.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H28 / 8月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4
車名 N-BOX	グレード G・Lパッケージ	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 660	型式 DBA-JF1	通称 型式	内装 A・B・C
車検 9年8月	燃料 ガソリン	ディーゼル	検出過剰品 () 等	
走行 14,986マイル	シフト ハイブリッド	AT		
外装色 パール	カラーNo. (NH875P)	エアコン AG・BG・WAG・()	装備品のみ O印 を記入	
()	内装色	乗車定員 4人	P・R・AW・サンルーフ・革シート	
ハンド 左・右	輸入 区分	ディーラー・並行	9,790円・預託金	エアロック・ABS・G・TV・モーター
セールスポイント 純正ナビ、TV、ETC、パワースライドドア、バックカメラ、革調シートカバー、プッシュスタート、スマートキー				
検査記入欄 コアサポート腐食穴、ダッシュ板ノリ跡、ルーム内キズ、ホイールCPキズ、下廻りサビペイント		修復歴 有・無		
		A キズ U ヘッドライト B キズ・ヘッド C 色あせ・ボケ D ガラスキズ W 補修跡 S サイズ C 腐食 X 交換済 XX 交換済		
		登録No. 月 日 まで(名義できる方)		
		車体番号 JF1-1870113		
FW トヨタ 丸 フレ 外装 小 丸 丸 丸 エアロ		シリアル No.		
内装 丸 シス ヤブレ コガ コガ穴 オーディオ穴		長さ 幅 高さ 最大積重量		
		cm cm cm Kg		