

2016 Honda Odyssey Absolute X Honda Sensing Advanced Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
RC1	2,356 cc		
YEAR / REG.	MILEAGE		
2016/03	73,633 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
RC1-1115082	483 × 182 × 169 cm		
SALES POINTS			
Alloy Wheels		Cruise Control	
Pre-Collision Braking		Back Camera	
Navigation System			
INSPECTOR REPORT			
Minor exterior scratches			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H28/3月	メーカー ホンダ	ドア枚数 5	ボディ形状 ミニバン/バンボックス	評価値 4
車名 オデッセイ	グレード アブソルート・Xホンダセンシング アドバンスドパッケージナビTV 全方 位カメラ 天井モニター 両側電動	駆動区分 2WD 4WD		
車歴 自用・その他()	排気量 2400 cc	型式 RC1	通称 正式	内装 A・B・C
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)	
走行 73,633 km	シフト フロア	AT		
外装色 クリスタルブラックパール	カラーNo. QD・AAG・WAG・()	乗車定員 7人	装備品のみ O印 を記入	
内装色 ()	ドア 左・(開) 右・(開)	ディーラー 走行	14,420円	エレクトリック ABS ESP サンルーフ 車シート ス
セールスポイント				
純正ナビ フルセグテレビ 全方位カメラ フリップダウンモニター 衝突軽減ブレーキ 両側電動スライドドア スマートキー プッシュスタート パワーシート コンビシート オットマン LEDヘッドライト フォグ ETC 純正アルミ				
修復歴 有・()				
検査記入欄				
外装小キズ				
A キズ U ヘッドランプ B キズ・ヘッド P 熱あせり・サビ Q ガラスキズ W 補修跡 S サビ C 腐食 X 交換部 YX 交換部 登録No. 月 日 までに名義できる方 車体番号 RC1-1115082				
FR	トボ石	傷A	フレ	外装
内装	ゴキ	シス	ヤブレ	コグ
				コグ穴
				オーディオ穴
				スレ
				エアロ
				シリアル
				No.
				長さ
				幅
				高さ
				最大積載量
				kg