

2016 Honda Step Wagon Spada Spada Advance Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-RP3	DISPLACEMENT 1,496 cc		
YEAR / REG. 2016/06	MILEAGE 106,300 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Purple	BODY TYPE Minivan		
CHASSIS NO. 1040523	DIMENSIONS (L X W X H) 474 × 170 × 184 cm		
SALES POINTS			
Alloy Wheels Navigation System		Cruise Control Rear Seat Entertainment (Rear Entertai...	
INSPECTOR REPORT			
Steering wheel wear, minor scuff on bumper bottom.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H28		メーカー ホンダ		ドア枚数 5	ボディ形状 ミニバンワンボックス	年価 4																				
6月		車名 ステップワゴンスパダ		グレード スパダアドバンスパッケージ	駆動区分 2WD																					
車種 自家用・その他 ()	排気量 1500 cc	型式 DBA-RP3	通称 ステップワゴン	内装 A・B・C																						
年 -	月 -	日 -	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書等)																					
走行 106,300 km	年 2016	月 06	日 00	インパネ	AT																					
外装色 パープル	カラーNo. ()	エアコン	AG・AG・WAG ()	装備品のみ O印 を記入																						
内装色 ()	乗車定員 7人	リサイクル料	10,230円	預託料	エブリック	その他																				
セールスポイント																										
純正ナビ 地デジTV バックカメラ 7人乗り 両側パワースライドドア ETC				修復歴 有・無																						
検査記入欄				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ/サレ</td><td>B</td><td>キズ/ヘコ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換品</td><td>XX</td><td>交換時</td> </tr> </table>			A	キズ	U	ヘコミ/サレ	B	キズ/ヘコ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換時
A	キズ	U	ヘコミ/サレ	B	キズ/ヘコ	P	色あせ/ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換時																	
ハンドルスレ バンパーA				登録No. 1040523																						
FW トビ石				シリアル No.																						
内装 シロ				車種 cm																						