

2016 Honda Step Wagon Spada Spada Honda Sensing		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-RP3	DISPLACEMENT 1,496 cc		
YEAR / REG. 2016/10	MILEAGE 87,070 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Purple	BODY TYPE Minivan		
CHASSIS NO. RP3-1107154	DIMENSIONS (L X W X H) 474 × 170 × 184 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Front Camera Navigation System		Power Sliding Doors (Both Sides) (Both... Adaptive Cruise Control Back Camera Rear Seat Entertainment (Rear Entertai...	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H28/10月	メーカー ホンダ	ドア数 5	ボディ形状 ミニバン/ワンボックス	評価点 4
車名 ステップワゴンスパダ	グレード スパダ・ホンダ センシング	駆動方式 2WD 4WD	内装 A・B・C	
車種 自動車・その他 ()	排気量 1500 cc	型式 DBA-RP3	通称 型式	
年 9	月 10	日 10	走行 87,070 km	燃料 ガソリン
色 パール	カラーNo. AAG・WAG・()	エンジン AT	変速機 AT	後日送り品 (保証書・取扱説明書 等)
外装色 プレミアムスパイラル・パール	内装色 A・AAG・WAG・()	乗車定員 7人	オプション サンルーフ	車シート
左・右・両 左・右	ディーラー 10,230円	ボディ色 A・B・C	キーレス	
セールスポイント				
純正9インチナビ/フリップダウンモニター/衝突安全装置/両側電動スライドドア/車線逸脱防止支援システム/ヘッドランプLED/Bluetooth接続/TC/BD付ABS				
検査記入欄				
外装AU				
修復歴 有・無				
A 今文 U ヘッドランプ B キズ・へこみ P 色あせ・汚れ Q ガラスキズ W 修理跡 S サビ C 腐食 X 交換品 YX 交換済				
車体番号 RP3-1107154				
内装 A・B・C				
シリアル No.				
重量 cm cm cm Kg				