

2016 Honda Step Wagon Spada Stepwgn Spada 1.5 Advance PKG__		OVERALL		4
		EXTERIOR	INTERIOR	
		-	-	
MODEL CODE DBA-RP3		DISPLACEMENT 1,496 cc		
YEAR / REG. 2016/01		MILEAGE 61,804 km		
DOORS 5		SEATS 7		
DRIVETRAIN 2WD (FF)		TRANSMISSION AT		
FUEL Petrol		STEERING Right		
EXTERIOR COLOR Other		BODY TYPE Minivan		
CHASSIS NO. RP3-1031545		DIMENSIONS (L X W X H) 473 × 169 × 184 cm		
SALES POINTS				
Alloy Wheels Cruise Control Back Camera		Power Sliding Doors (Both Sides) (Drive... Adaptive Cruise Control Navigation System		
INSPECTOR REPORT				
Exterior has minor scratches and dents. Door mirrors have scratches. Interior trim and cabin are stained. Seats show scuffs. Front windshield has scratches, stone chips, cracks, and repair marks, replacement recommended. Interior has scratches, stains, burn holes, scuffs, and tears.				

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成28年1月	車名・グレード ステップワゴンスパダ ステップワゴンスパダ ステップワゴンスパダ	2WD 4WD (4)	評価点 (4)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-RP3	排気量 1500 CC	ドア 5 定員 7人 外装 C 内装 B
車種 自家用	シフト CAT	セールスポイント (正常に機能するものに限りです)	
車検 令和9年1月(日)	冷暖 AAC	スマートキー・ETC・パワースライドドア(両側) メモリーナビ・バックカメラ	
走行 6万1千804 km	燃料 ガソリン	諸備品 (純正品に限り○をつけてください)	
色 ブラック	色コード NH812P	(PS) (PW) (ABS) (エアB) (AW) SR ナビ TV カワ	
R券 10,230 円		新車保証書 有・無	
注意事項申告欄			
外装 小A・小U ドアミラー キズ 内張り 汚れ 室内 汚れ シート すれ			
フロントガラス キズ・傷・ヒビ割・リペア跡・X痕 内装 キズ・傷・コゲ・穴・変色・キレ・破れ			
車台番号 1031545	A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済		
登録番号 成田 300 と 7184	型式指定番号 18043	車検区分番号 0002	車検区分 長さ 473 mm 幅 169 mm 高さ 184 mm