

| 2016 SUBARU Levorg 1.6 GT EyeSight S Style                                                                                                                                                |                                              | OVERALL                                      |          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------------------------------------------|----------|
|                                                                                                                                                                                           |                                              | 4                                            |          |
|                                                                                                                                                                                           |                                              | EXTERIOR                                     | INTERIOR |
|                                                                                                                                                                                           |                                              | -                                            | -        |
| MODEL CODE<br>DBA-VM4                                                                                                                                                                     | DISPLACEMENT<br>1,599 cc                     |                                              |          |
| YEAR / REG.<br>2016/07                                                                                                                                                                    | MILEAGE<br>102,692 km                        |                                              |          |
| DOORS<br>5                                                                                                                                                                                | SEATS<br>5                                   |                                              |          |
| DRIVETRAIN<br>4WD                                                                                                                                                                         | TRANSMISSION<br>AT                           |                                              |          |
| FUEL<br>Petrol                                                                                                                                                                            | STEERING<br>Right                            |                                              |          |
| EXTERIOR COLOR<br>Pearl White                                                                                                                                                             | BODY TYPE<br>Station Wagon                   |                                              |          |
| CHASSIS NO.<br>VM4-083313                                                                                                                                                                 | DIMENSIONS (L X W X H)<br>469 × 178 × 149 cm |                                              |          |
| SALES POINTS                                                                                                                                                                              |                                              |                                              |          |
| Alloy Wheels<br>Cruise Control                                                                                                                                                            |                                              | Adaptive Cruise Control<br>Navigation System |          |
| INSPECTOR REPORT                                                                                                                                                                          |                                              |                                              |          |
| Exterior: Noticeable scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains and dirt are present. Repair History: No abnormalities in the frame. |                                              |                                              |          |

[illegible]