

2016 SUBARU Levorg Levorg 1.6 GT EyeSight S Style 4WD		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-VM4	DISPLACEMENT 1,599 cc		
YEAR / REG. 2016/01	MILEAGE 21,608 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Station Wagon		
CHASSIS NO. VM4-064310	DIMENSIONS (L X W X H) 469 × 178 × 149 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Cruise Control	
INSPECTOR REPORT			
Right door mirror malfunction. Wheel scratches. Interior dirt and pet hair. Seat sagging. Steering wheel scuffs. Front glass has scratches, stone chips, cracks, repair marks, and requires replacement. Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成28年1月	車名・グレード レヴォーグ 1.6GTアイサイトSスタイル	2WD (4WD)	評価点 (4.5)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-VM4	排気量 1600 CC	ドア 5 定員 5人 積載 kg
車種 自家用	シフト FAT	外装 B	内装 C
車検 年 月 (日)	冷暖 AAC	セールスポイント (正常に機能するものに限ります)	
走行 2万1千608 km	燃料 ガソリン	ETC アイサイト レーダークルーズコントロール	
色 パール	色コード K1X/J20	諸備品 (純正品に限り○をつけてください)	
R券 13,610 円		(PS) (PW) (BS) (AB) (AW) SR ナビ TV カワ	
注意事項申告欄		新車保証書 有・無	
右ドアミラー・傷・不具合			
ホイール・キズ			
外装 小A・小U			
室内 汚れ			
室内 ベットの毛			
シート へたり			
ハンドル すれ			
フロントガラス キズ・傷・ヒビ割・リペア跡・X要 内装 キズ・傷・ヒビ割・コゲ・穴・変色・キレ・破れ		A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済 型式検査番号 17723 車検区検査番号 1006 重量 469 kg 長さ 178 cm 高さ 149 cm	
車台番号 064310			
登録番号			