

2016 MAZDA Axela Sedan XD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
LDA-BM2FP	2,188 cc		
YEAR / REG.	MILEAGE		
2016/02	64,700 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Red	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
BM2FP-100131	458 × 180 × 146 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Leather Seats (Perforated Leather)		Pre-Collision Braking	
Adaptive Cruise Control		Navigation System	
Bose Sound System (AUDIOPILOT2 + C...			
INSPECTOR REPORT			
Minor scratches, trunk opener switch malfunction.			

年式登録番号 H28 / 2 月		メーカー マツダ		ドア数 4		セダン		年式区分 2WD 4WD		4	
車種 自動車・その他 ()		排気量 2200		CC 形式 LDA-BM2FP		運転形式		内装 A・B・C			
車検 - 年 月 日		燃料 ガソリン ハイブリッド ()		型式 マル		後付部品 (保証書・取扱説明書 等)					
走行 (前年・前月・前日)		車検 6.4 / 7.00		マイル フロア 6 AT							
外装色 ソルレッドパールメタリック ()		カラーNo. ()		モニター ()		新着品のみ O 印を記入					
内装色 ()		5人		()		()					
左・右 ()		ディーラー 走行 11,070 円		買値 エアック		()					
セールスポイント											
本革シート/キーレスエントリー/ABS/運転席エアバック/助手席エアバック/サイドエアバック/モロナビ付/ヒルセグT/V/衝突被害軽減ブレーキ/TCF/アイドリングストップ/スマートキー/オートクルーズコントロール/LEDヘッドライト/横滑り防止装置 (ESC) /パワーシート/シートヒーター/DVD再生/ミュージックプレーヤー/接続可CD/バックカメラ/障害物センサー											
検査記入欄											
小傷 トランクオープンスイッチ不良											
車体番号 BM2FP-100131											
車体番号 BM2FP-100131											
車体番号 BM2FP-100131											