

2016 MAZDA Axela Sport 22XD L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-BM2AS	DISPLACEMENT 2,188 cc		
YEAR / REG. 2016/09	MILEAGE 94,764 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Station Wagon		
CHASSIS NO. BM2AS-100103	DIMENSIONS (L X W X H) 447 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Leather Seats (Perforated Leather)		Pre-Collision Braking	
Adaptive Cruise Control		Bose Sound System (AUDIOPILOT2 + C...	
INSPECTOR REPORT			
Minor undercarriage damage, program changes when stationary, Trim A, seat scuffs and wrinkles, steering wheel scuffs, headliner scuffs, headlight cloudiness, left and right mirrors malfunctioning.			

ORIGINAL JAPANESE AUCTION SHEET

年式車種 H28 / 9月	メーカー マツダ	ドア数 5	ボディ形状 ステーションワゴン	評価点 4
車名 アクセラスポーツ	グレード 22XD L パッケージ	駆動方式 2WD	燃費区分 490	
車種 自家用・その他 ()	排気量 2180 CC	型式 LDA-BM2AS	通称 2WD	内装 A・B・C
車検 9年9月 / 抹消	燃料 ガソリン	変速機 オートマ	後付部品 ()	
走行 94,764 km	シフト AT			
外装色 ブルー	カラーNo. (45B)	エアコン AG・AC・WAG ()	後付品のみ O印 を記入	
内装色 ()	内装 ブラック	乗車定員 5人	PS	ABS
走行 左・右	ディーラー・走行 11,070 km	リサイクル料	エアロ	ナビ
セールスポイント				
ヘッドアップディスプレイ サンルーフ シートヒーター ステアリングヒーター BOSE				
検査記入欄				
修理履歴				
A キズ B ヘッドレスト C キズ・へこみ D 色あせ・汚れ E ガラスキズ				
W 経年劣化 S サビ C 腐食 X 交換部 YX 交換済				
名義中				
月 日 までにご覧できる方				
車検番号 BM2AS-100103				
シリアル No.				
最大積載量 0 kg				