

2016 Mazda Carol 5D GL		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
HB36S	658 cc		
YEAR / REG.	MILEAGE		
2016/02	114,996 km		
DOORS	SEATS		
5	4		
TRANSMISSION	FUEL		
AT	Petrol		
STEERING	EXTERIOR COLOR		
Right	Brown		
BODY TYPE			
Kei			
CHASSIS NO.	DIMENSIONS (L X W X H)		
HB36S-208062	340 × 148 × 148 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Mirror faded, seat stains (medium), driver's seat sagging (medium), carpet scuffs (medium), steering wheel scuffs (medium), console A (small), front glass edge air bubbles, rear only studless tires.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H28 / 2月	メーカー マツダ 車名 キャロル	ドア枚数 5	ボディ形状 軽四	評価点 4
車種 自家用・その他 ()	排気量 660 CC	型式 HB36S	通称 型式	内装 A・B
車検 9年2月 / 抹消	燃料 ガソリン	ディーゼル	検閲済み (保証書・取扱説明書 等)	
走行 114,996マイル	インパネ	AT		
外装色 アーバンブラウンパールメタリック	カラーNo. ()	エアコン A・A・G・W・A・G・()	装備品のみ O印 を記入	
()	内装色 ()	乗車定員 人	PS	サンルーフ
左・右 左・右	ディーラー ディーラー	走行 7,220円・現行無	エアロック	ナビ
セールポイント CD/E/TC横滑り防止装置 (ESC) /運転席エアバック / 盗難防止システム/キーレスエントリー/A B S /助手席エアバック/衝突被害軽減ブレーキ/衝突安全ボディアイドリングストップ/シートヒーター				
検査記入欄 ミラー色確認 シートしめ 運転席へたひ カーペットずれ ハンドルのずれ コンソールA ドアガラスの劣化 リアのめすタックレスタイヤ				
検査結果 A キズ U ヘッドライト B キズ・ヘッドライト C 色あせ・ボケ D ガラスキズ W 補修 S サイズ C 腐食 X 交換 Y 交換済				
登録No. 月 日 までにも変更できる方				
車体番号 HB36S-208062				
シリアル No.				
車種 長さ cm 幅 cm 高さ cm 最大積載量 Kg				