


2016 MAZDA CX-3 XD		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-DK5FW	DISPLACEMENT 1,498 cc		
YEAR / REG. 2016/07	MILEAGE 97,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. DK5FW-130435	DIMENSIONS (L X W X H) 428 × 177 × 155 cm		
SALES POINTS			
Alloy Wheels Back Camera Navigation System		Pre-Collision Braking Cruise Control	
INSPECTOR REPORT			
Navigation monitor cloudy/hazy, interior dirty, seat edges worn, door mirror scratches			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H28 / 7月	メーカー マツダ	ドア数 5	ボディ形状 SUV/クワカン	評価点 3.5
車名 CX-3	グレード XD マツダコネクナビ バックカメラ LED	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1500 CC	型式 LDA-DK5FW	通称 形式	内装 A・②・C
燃料 ガソリン	デカゼル	後日選り込み (保証書・取扱説明書 等)		
走行 97,000 km	フロア AT			
外装色 ジェットブラックマイカ	カラーNo.	②D・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5 人	②	③	④ サンルーフ ⑤ 革シート
① 左・② 右 ③ 左・④ 右	ディーラー ⑤ 走行	⑥ 10,780円	⑦ エアロック ⑧ ⑨ ⑩ ⑪ ⑫	⑬ ス
セールスポイント キーレスエントリー/ABS/運転席エアバック/助手席エアバック/メモリーナビ他/フルセグTV/ETC/アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/LEDヘッドライト/横滑り防止装置(ESC)/DVD再生/ミュージックプレーヤー接続可/CD/バックカメラ				
検査記入欄 ナビモニター曇り ルーム内一部汚れ シートフチへたり ドアミラーキズ		修復歴 有・⑤		
車体番号 DK5FW-130435		A キズ U ヘッドランプ B キズ・ヘッド P 熱気センサー Q ガラスキズ W 修理跡 S サビ C 腐食 X 交換部 YX 交換部 登録No. 月 日 までに名義できる方 車体番号 シリアル No.		
FW トビ石 ①A フレ ②A 小 A・U ホイル A・曲 A・フレ エアロ 内装 ヨゴレ シス ヤブレ コグ コグ穴 オーディオ穴 スレ	長さ cm	幅 cm	高さ cm	最大積載量 kg