

2016 MAZDA CX-3 XD Touring L Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DK5FW	1,498 cc		
YEAR / REG.	MILEAGE		
2016/01	97,852 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
DK5FW-124268	428 × 177 × 155 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Navigation System			
INSPECTOR REPORT			
Minor scratches and dents on the exterior.			

初年度登録	メーカー マツダ	ドア数 5	ボディ形状 SUV/クワン	評価点																																																			
H28 / 1月	車名 CX-3	グレード XD ツーリング Lパッケージ	駆動方式 2WD 4WD	9.5																																																			
車種 自動車・その他 ()	排気量 1500 CC	型式 DK5FW	燃費 都市 混合 高速	内装 A・⑨・C																																																			
年式 - 年 月 日	燃料 ガソリン ハイブリッド ()	償還月数 (保証年・取扱説明書 等)																																																					
走行 97,852 km	シフト フロア 6 AT																																																						
外装色 クリスタルホワイトパールマイカ 34K	エンジン Q6・AAG・WAG・()	装備品のみ O印 を記入																																																					
内装色 黒革調	乗車定員 5人	サンルーフ 革シート																																																					
左・右 左・右	輸入 ディーラー 走行 10,780円・新車税	エアロ																																																					
セールスポイント																																																							
純正ナビ		修復歴 有・⑥ <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみサシ</td><td>B</td><td>キズ・へこみ</td><td>P</td><td>熱影響・ゆがみ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>修理跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換部</td><td>XX</td><td>交換済</td> </tr> </table>			A	キズ	U	へこみサシ	B	キズ・へこみ	P	熱影響・ゆがみ	G	ガラスキズ	W	修理跡	S	サビ	C	腐食	X	交換部	XX	交換済																															
A	キズ				U	へこみサシ	B	キズ・へこみ	P	熱影響・ゆがみ	G	ガラスキズ																																											
W	修理跡				S	サビ	C	腐食	X	交換部	XX	交換済																																											
バックカメラ																																																							
衝突軽減ブレーキ/レーンアシスト																																																							
レーダークルーズコントロール																																																							
ブラインドスポットモニター																																																							
ハーフレザシート		登録年 月 日 家で名義である																																																					
シートヒーター		車体番号 DK5FW-124268																																																					
検査記入欄		名義 車種 型式 年式 月 日 車体番号 DK5FW-124268																																																					
外装小A,U		修復歴 有・⑥																																																					
<table border="1"> <tr> <td>FW</td><td>①</td><td>②</td><td>③</td><td>④</td><td>⑤</td><td>⑥</td><td>⑦</td><td>⑧</td><td>⑨</td><td>⑩</td><td>⑪</td><td>⑫</td><td>⑬</td><td>⑭</td><td>⑮</td><td>⑯</td><td>⑰</td><td>⑱</td><td>⑲</td><td>⑳</td><td>㉑</td><td>㉒</td><td>㉓</td><td>㉔</td><td>㉕</td><td>㉖</td><td>㉗</td><td>㉘</td><td>㉙</td><td>㉚</td><td>㉛</td><td>㉜</td><td>㉝</td><td>㉞</td><td>㉟</td><td>㊱</td><td>㊲</td><td>㊳</td><td>㊴</td><td>㊵</td><td>㊶</td><td>㊷</td><td>㊸</td><td>㊹</td><td>㊺</td><td>㊻</td><td>㊼</td><td>㊽</td><td>㊾</td><td>㊿</td> </tr> </table>		FW	①	②	③	④	⑤	⑥	⑦	⑧	⑨	⑩	⑪	⑫	⑬	⑭	⑮	⑯	⑰	⑱	⑲	⑳	㉑	㉒	㉓	㉔	㉕	㉖	㉗	㉘	㉙	㉚	㉛	㉜	㉝	㉞	㉟	㊱	㊲	㊳	㊴	㊵	㊶	㊷	㊸	㊹	㊺	㊻	㊼	㊽	㊾	㊿	修復歴 有・⑥		
FW	①	②	③	④	⑤	⑥	⑦	⑧	⑨	⑩	⑪	⑫	⑬	⑭	⑮	⑯	⑰	⑱	⑲	⑳	㉑	㉒	㉓	㉔	㉕	㉖	㉗	㉘	㉙	㉚	㉛	㉜	㉝	㉞	㉟	㊱	㊲	㊳	㊴	㊵	㊶	㊷	㊸	㊹	㊺	㊻	㊼	㊽	㊾	㊿					