

2016 Mazda CX-3 XD Touring L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-DK5FW	DISPLACEMENT 1,498 cc		
YEAR / REG. 2016/03	MILEAGE 40,980 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE SUV		
CHASSIS NO. DK5FW-127311	DIMENSIONS (L X W X H) 428 × 177 × 155 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Driver's side mirror (A), seat wear, navigation monitor deterioration, door mirror housing discoloration.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H28/3月	メーカー マツダ	ドア枚数 5	ボディ形状 SUV/クワカン	評価点 4
車名 CX-3	グレード XD ツーリング L パッケージ	駆動区分 2WD 4WD		
車歴 自用・その他 ()	排気量 1490 cc	型式 LDA-DK5FW	通称 2WD	内装 A・B・C
車検 - - 年 月 / 日	燃料 ガソリン	デジ ハイブリッド	後日選り込み (62 番・取付印等)	
走行 40,980 km	シフト AT	ナビSD、手帳		
外装色 レッド	カラーNo. 41V	QD・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5 人	(62) (63) (64) (65)	サンルーフ	革シート
左・前 左・前	ディーラー ディーラー	走行 10,780 km	エレクト エレクト	キーレス
セールスポイント ブッシュスタート、IS				
検査記入欄 Dミラー-A、シートスレ、ナビモニター劣化 ドアミラーハウジングアセ		修復歴 有・(66)		
		A キズ U ヘッドランプ B キズ・ヘッド P 乗客シート Q ガラスキズ W 後部座席 S サブ C 腐食 X 交換済 YX 交換済		
		登録No. 月 日 まで(名義できる方)		
		車体番号 DK5FW-127311		
内装 (67)		シス シス	ヤブレ ヤブレ	コグ コグ
エアロ エアロ		小 小	ホイール ホイール	エアロ エアロ
内装 (68)		シス シス	ヤブレ ヤブレ	コグ コグ
エアロ エアロ		小 小	ホイール ホイール	エアロ エアロ
内装 (69)		シス シス	ヤブレ ヤブレ	コグ コグ