

2016 MercedesBenz Benz B Class B180 / Sport / Late Model		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
246242	1,595 cc		
YEAR / REG.	MILEAGE		
2016/02	32,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WDD2462422J355503	440 × 179 × 155 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Cruise Control		Back Camera	
Navigation System			
INSPECTOR REPORT			
Exterior: Minor scratches and dents have been repaired, but some small scratches and dents remain. Interior: The cabin is clean with no noticeable stains. Repair history: No abnormalities in the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青森内のカー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H28/2月	メーカー メルセデス・ベンツ	ドア数 5	ボディ形状 ミニバン/ワンボックス	評価点 4
車名 Bクラス	グレード B180 / スポーツ / 後期型	車体番号 246242	重量 1600	燃料 ガソリン
用途 自家用	ディーラー 右	年式 9年3月	抹消 3/2	マイル 32,000
カラー カルサイトホワイト	カラーNo. ()	リサイクル料 19,120円	販売店 WDD2462422J355503	車種 AC
シフト フロア	AT	乗車定員 5人	長さ 440cm	幅 179cm

車検日返
(保証書・取説説明書等)

整備
エンジン
ブレーキ
サスペンション
ステアリング
その他

セールスポイント

査定員記入欄

※ダメージレベルに関する注意事項
ダメージレベルは、車検時に受けるダメージの目安です。ダメージレベルが大きい車は、修理費が高くなる可能性があります。また、ダメージレベルが大きい車は、中古車としての価値が下がります。そのため、中古車を購入する際には、ダメージレベルを確認することが重要です。

クオリティグレード説明
外装: 劣化するボディパネルは補修済みですが、小さなキズや凹みが残っています。
内装: 劣化する内装材は補修済みですが、小さなキズや凹みが残っています。
機体: 劣化する機体部品は補修済みですが、小さなキズや凹みが残っています。

車検合格保証書
青森県内では、青森県自動車検査所にて車検合格しています。