

2016 MercedesBenz GLC-CLASS GLC250 4MATIC Sport		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 253946C	DISPLACEMENT 1,991 cc		
YEAR / REG. 2016/02	MILEAGE 63,682 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. WDC2539462F032601	DIMENSIONS (L X W X H) 467 × 189 × 165 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Pre-Collision Braking Cruise Control Front Camera Back Camera		Roof Rails Power Seats (Front) Adaptive Cruise Control Parking Assist (Auto Steering) Side Camera Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

年式 H28 2月	メーカー メルセデス・ベンツ	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
車種 自家用・その他 ()	グレード GLC	型式 GLC250 4 マチックスポーツ	駆動方式 2WD	
乗車人数 8人	排気量 2000 cc	車体番号 253946C	登録区分 4WD	内装 A・B・C
走行 8年12月	燃料 ディーゼル	装備品 ナビ付	後付部品 (保証書・取扱説明書等)	
カラーNo. 197	エアコン AG・AC・WAG・()	コラム 9 AT	新車のみのO印を記入	
外装色 オプシアンブラック	内装色 ()	乗車人数 5人	サンルーフ	シート
左・前 左・前 左・前	走行 17,210 km	エンジン	エアコン	ナビ
セールスポイント				
レーダーセーフティパッケージ 純正ナビ フルセグ 360°カメラ ヘッドアップディスプレイ パワー テールゲート ドライブレコーダー シートヒーター アンビエントライト ETC2.0 ハーフレッガー				
修復歴 有・6				
検査記入欄				
A キズ B へこみ C サビ D 変色 E 汚れ F 傷 G 変形 H 欠損 I 他				
W 補修済 S サビ C 腐食 X 交換済 Y 交換済 Z 交換済				
名義中				
月 日 家でに名義で受取る方				
WDC2539462F032601				
内装 シロ	外装 シロ	ボディ シロ	エンジン シロ	変速機 シロ