

2016 Mitsubishi Delica D5 D Power Package		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CV1W	DISPLACEMENT 2,267 cc		
YEAR / REG. 2016/04	MILEAGE 8,440 km		
DOORS 5	SEATS 8		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Minivan		
CHASSIS NO. CV1W-1105319	DIMENSIONS (L X W X H) 473 × 180 × 187 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Back Camera Rear Seat Entertainment (Rear seat 9-in...		Power Sliding Doors (Both Sides) (Both... Cruise Control Navigation System	
INSPECTOR REPORT			
Other rims have partial scuffs, scratches, and minor deformation.			

ORIGINAL JAPANESE AUCTION SHEET

登録済の車両情報 / JAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H28/4月	メーカー 三菱	ドア数 5	ボディ形状 ミニバン/ワンボックス	評価点 5
車名 デリカD:5	グレード D パワーパッケージ			
用途 自用	右	CV1W	2200	ディーゼル
年 9年	月 4月	日 8日	走行距離 4WD	AC
カラーNo. シルバーパール	リサイクル料 14,710円	車台番号 CV1W-1105319	長さ cm	幅 cm
シフト インパネ	AT	乗車定員 8人	高さ cm	重量 Kg

（ ） 保証書・取扱説明書等

装備
① ② ③ サルーフ ④ シート ⑤ エアコン ⑥ クルーズ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿

セールスポイント
ワンオーナー・3月シート・LEDバックカメラ・ETC/ETD・キセノン・ディスチャージ・運転席エアバック・防鎖止システム・ス마트キー・ギアレスエントリー・A/B/S助手席エアバック・メモリーナビ・フルセグTV・VW・D・電動リアゲート・V・D・電動両側・電動リフター・電動両側電動スライドドア

査定員記入欄

※ダメージレベルに関する注意事項
① 傷の深さ
② 傷の長さ
③ 傷の幅
④ 傷の位置
⑤ 傷の色
⑥ 傷の形状
⑦ 傷の大きさ
⑧ 傷の広がり
⑨ 傷の入り込み
⑩ 傷の凹凸
⑪ 傷の剥離
⑫ 傷の脱落
⑬ 傷の欠損
⑭ 傷の变形
⑮ 傷の歪み
⑯ 傷の折れ
⑰ 傷の割れ
⑱ 傷のひび
⑲ 傷の亀裂
⑳ 傷のさび
㉑ 傷の錆
㉒ 傷の腐食
㉓ 傷の穴
㉔ 傷の凹
㉕ 傷の凸
㉖ 傷の歪
㉗ 傷の曲
㉘ 傷の折
㉙ 傷の割
㉚ 傷のひ
㉛ 傷の亀
㉜ 傷のさ
㉝ 傷の錆
㉞ 傷の腐
㉟ 傷の穴
㊱ 傷の凹
㊲ 傷の凸
㊳ 傷の歪
㊴ 傷の曲
㊵ 傷の折
㊶ 傷の割
㊷ 傷のひ
㊸ 傷の亀
㊹ 傷のさ
㊺ 傷の錆
㊻ 傷の腐
㊼ 傷の穴
㊽ 傷の凹
㊾ 傷の凸
㊿ 傷の歪

クオリティグレード説明
外装: 外装に傷や汚れ等がない状態を指します。
内装: 内装に傷や汚れ等がない状態を指します。
ボディ: ボディに傷や汚れ等がない状態を指します。

車両状態の図解
① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿