

2016 MITSUBISHI Outlander PHEV G Safety Package		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GG2W	DISPLACEMENT 1,998 cc		
YEAR / REG. 2016/02	MILEAGE 98,333 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. GG2W-0308987	DIMENSIONS (L X W X H) 470 × 180 × 171 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Front Camera Back Camera		Roof Rails Adaptive Cruise Control Side Camera Navigation System	
INSPECTOR REPORT			
Right center pillar repaired (bodywork/paint). Interior and exterior scuffs and scratches repaired.			

新車登録		三菱		ドア数 5		SUV/クロカン		年式区分		評価点																									
H28 / 2月		車名 アウトランダーPHEV		グレード Gセーフティパッケージ		車種区分 2WD		R																											
車種 国産車・その他 ()		排気量 2000 CC		型式 GGZW		運転形式		内装 A・C・G																											
車検 年 月 日		燃料 ガソリン		ディーゼル		後付選装品 (保証書・取扱説明書 等)																													
走行 (国にオーソライズした車・交換・追加・変更・修理)		シフト																																	
年 月 日		マイル		フロア AT																															
外装色		カラーNo.		() AQ・AG・WAG・()																															
パールホワイト ()		内装色		新着品のみ O印 を記入																															
()		標準定員		5 人																															
左・右・後		ディーラー		走行		11,100円・ 税別																													
セールスポイント																																			
ケンウッドナビ 360°カメラ フルセグ Bluetooth 電動シート LEDヘッドライト 左右ステアヒーター ステアリングヒーター ETC 衝突軽減ブレーキ																																			
検査記入欄																																			
右センタービラーBP 内外装スレスズ補修																																			
修復歴 ① 無 <table border="1"> <tr> <td>A</td> <td>火災</td> <td>U</td> <td>洪水・水害</td> <td>B</td> <td>自然・火災</td> <td>D</td> <td>地震・落石・倒木</td> <td>G</td> <td>盗・入</td> <td>W</td> <td>盗・入</td> </tr> <tr> <td>W</td> <td>修繕品</td> <td>C</td> <td>ヤブ</td> <td>C</td> <td>盗取</td> <td>X</td> <td>交換</td> <td>XX</td> <td>交換</td> <td></td> <td></td> </tr> </table> 車種区分 月 日 までに有責である 車検番号 GGZW-G308987												A	火災	U	洪水・水害	B	自然・火災	D	地震・落石・倒木	G	盗・入	W	盗・入	W	修繕品	C	ヤブ	C	盗取	X	交換	XX	交換		
A	火災	U	洪水・水害	B	自然・火災	D	地震・落石・倒木	G	盗・入	W	盗・入																								
W	修繕品	C	ヤブ	C	盗取	X	交換	XX	交換																										
<table border="1"> <tr> <td>FW</td> <td>①</td> <td>②</td> <td>③</td> <td>④</td> <td>⑤</td> <td>⑥</td> <td>⑦</td> <td>⑧</td> <td>⑨</td> <td>⑩</td> <td>⑪</td> </tr> <tr> <td>内装</td> <td>①</td> <td>②</td> <td>③</td> <td>④</td> <td>⑤</td> <td>⑥</td> <td>⑦</td> <td>⑧</td> <td>⑨</td> <td>⑩</td> <td>⑪</td> </tr> </table>												FW	①	②	③	④	⑤	⑥	⑦	⑧	⑨	⑩	⑪	内装	①	②	③	④	⑤	⑥	⑦	⑧	⑨	⑩	⑪
FW	①	②	③	④	⑤	⑥	⑦	⑧	⑨	⑩	⑪																								
内装	①	②	③	④	⑤	⑥	⑦	⑧	⑨	⑩	⑪																								