

2016 Nissan NV100 Clipper DX GL Package		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HBD-DR17V	DISPLACEMENT 658 cc		
YEAR / REG. 2016/08	MILEAGE 132,882 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. DR17V-133730	DIMENSIONS (L X W X H) 340 × 148 × 190 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Trim scratches, headliner scratches, cargo area scratches, exterior dullness, steering wheel wear, seat stains, unpleasant interior odor, front windshield stone chips, interior dirt, interior wear.			

ORIGINAL JAPANESE AUCTION SHEET

H28/8月		メーカー 日産		ドア枚数 5	ボディ形状 軽四	評価点 3																				
車名 NV100クリッパーバン		グレード DX GLパッケージ		駆動方式 4WD																						
車種 自家用・その他 ()	積気量 660 CC	型式 HBD-DR17V	通称形式	内装 A・B	C																					
車検 - 年 月	燃料 ガソリン	ディーゼル	検印選り品 (保証書・取扱説明書 等)																							
走行 132,882 マイル	シフト AT																									
外装色 ホワイト	カラーNo. ()	エアコン	装備品のみ O印 を記入																							
()	内装色 ()	Qd・AAG・WAG・()	サンルーフ 車シート																							
左・右	輸入区分	ディーラー・並行	7,860円・預託金	エアロック	ナビ	TV キーレス																				
セールスポイント																										
検査記入欄			修復歴 有・無																							
修理交付は修理後10日経過後のみ。 トリムキズ 天板キズ 荷室キズ 外装ツヤナシ ハンドルスレ シートシミ 室内汚損			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ割れ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘコみ割れ	B	キズ・ヘコみ	P	色あせ・ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ割れ	B	キズ・ヘコみ	P	色あせ・ボケ	Q	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
登録No. 月 日			名義中																							
車体番号 DR17V-133730			シリアル No.																							
FW	トビラ	座席	フレ	外装	小	ホイール	エアロ																			
内装	シス	ヤブレ	コガ	コガ穴	オーディオ	その他	その他																			
長さ	幅	高さ	最大積載量																							
cm	cm	cm	Kg																							