

2016 SUBARU Stella 660 L Smart Assist		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LA150F		DISPLACEMENT 658 cc	
YEAR / REG. 2016/06		MILEAGE 51,000 km	
DOORS 5		SEATS 4	
DRIVETRAIN 2WD (FF)		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR Pink		BODY TYPE Hatchback	
CHASSIS NO. LA150F-0011622		DIMENSIONS (L X W X H) 340 × 148 × 163 cm	
SALES POINTS			
Pre-Collision Braking			
INSPECTOR REPORT			
Interior scuffs, some rust underneath, wheel scratches, puncture repair kit missing.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H28/6月		メーカー スバル		ドア枚数 5		ボディ形状 コンパクト/ハッチバック		評価点 4	
車名 ステラ		グレード 660 L スマートアシスト キーレス ETC 衝突被害 軽減ブレーキ		駆動区分 2WD 4WD					
車種 自家用・その他 ()		排気量 660 cc		型式 DBA-LA150F		通称 型式		内装 A・⑨・C	
車検 9年11月		燃料 ガソリン		ディーゼル		後日送付品 (保証書・取扱説明書 等)			
走行 51,000 km		インパネ		CVT					
外装色 ピンク		カラーNo. ()		エアコン (A)・AAG・WAG・()		新着品のみ O印 を記入			
内装色 ()		乗車定員 4人		PS		AW		サンルーフ	
左・右 左・右		ディーラー		走行		ナビ		TV	
販売店 8,780円		預託金		エアロック		ナビ		TV	
セールスポイント									
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/衝突被害軽減ブレーキ/ETC/アイドリングストップ/寒冷地仕様/横滑り防止装置 (ESC) /ベンチシート									
検査記入欄									
ルーム内スレ									
下廻り一部サビ									
ホイールキズ									
パンク修理キット欠									
修復歴 有・⑨									
A キズ U ヘッドライト B キズ・ヘッド C 色あせ・サケ G ガラスキズ									
W 補修跡 S サビ C 腐食 X 交換部 XX 交換済									
登録No. 月 日 までに名変できる方									
名変中									
車検番号 LA150F-0011622									
FW トピ石 備A フレ 外装 小 赤いル エアロ シリアル No.									
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ									
長さ 幅 高さ 最大積重量 Kg									