


2016 Suzuki Hustler G		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DAA-MR41S	658 cc		
YEAR / REG.	MILEAGE		
2016/11	44,350 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
MR41S-226931	340 × 148 × 167 cm		
SALES POINTS			
Pre-Collision Braking			
INSPECTOR REPORT			
Front repair history, minor interior scratches, right front instrument panel distortion.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H28/11月	メーカー スズキ	ドア枚数 5	ボディ構造 軽四	評価点 R																				
車名 ハスラー	グレード G	駆動区分 4WD																						
車種 自家用・その他 ()	排気量 660 cc	型式 DAA-MR41S	通称 軽四	内装 A・⑨・C																				
車検 - - 年 / 月	燃料 ハイブリッド	ディーゼル ()	後日送り品 () 書・取扱説明書 等 ()																					
走行 44,350 km	インパネ	AT																						
外装色 ブラック	カラーNo. (Z) 3	エアコン AG・QG・WAG・()	新着品のみ O印 を記入																					
内装色 ()	乗車定員 4人	PS	AW	サンルーフ																				
ハンド 左・右	ディーラー 並行	ナビ	TV	カーレス																				
セールスポイント スベアキー		8,400円・預託金																						
検査記入欄 F修復歴 ルーム内一部キズ、右フィンパネヒズミ																								
		<table><tr><td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ・へこみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td></tr><tr><td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換歴</td><td>XX</td><td>交換済</td></tr></table>			A	キズ	U	へこみ/サレ	B	キズ・へこみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ・へこみ	P	色あせ/ボケ	G	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換済															
		登録No. 月 日 までに名変できる方																						
		車検番号 MR41S-226931																						
FW (トビ) ()		ワレ	外装 () ()	エアロ No.																				
内装 ()	シミ	ヤブレ	コガ	コガ穴																				