

|                                                                                                                                            |                                              |                                                                |          |
|--------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------------------------------------------------------------|----------|
| 2016 Suzuki Solio Bandit Hybrid MV                                                                                                         |                                              | OVERALL                                                        |          |
|                                                                                                                                            |                                              | 4                                                              |          |
|                                                                                                                                            |                                              | EXTERIOR                                                       | INTERIOR |
|                                                                                                                                            |                                              | -                                                              | -        |
| MODEL CODE<br>MA36S                                                                                                                        | DISPLACEMENT<br>1,242 cc                     |                                                                |          |
| YEAR / REG.<br>2016/10                                                                                                                     | MILEAGE<br>43,133 km                         |                                                                |          |
| DOORS<br>5                                                                                                                                 | SEATS<br>5                                   |                                                                |          |
| TRANSMISSION<br>AT                                                                                                                         | FUEL<br>Hybrid (Petrol)                      |                                                                |          |
| STEERING<br>Right                                                                                                                          | EXTERIOR COLOR<br>Other                      |                                                                |          |
| BODY TYPE<br>Minivan                                                                                                                       |                                              |                                                                |          |
| CHASSIS NO.<br>MA36S-629183                                                                                                                | DIMENSIONS (L X W X H)<br>371 × 163 × 175 cm |                                                                |          |
| SALES POINTS                                                                                                                               |                                              |                                                                |          |
| Alloy Wheels<br>Back Camera                                                                                                                |                                              | Power Sliding Doors (Both Sides) (Both...<br>Navigation System |          |
| INSPECTOR REPORT                                                                                                                           |                                              |                                                                |          |
| Exterior: Some noticeable scratches and dents. Interior: Some noticeable stains in parts. Accident History: No abnormalities in the frame. |                                              |                                                                |          |

[illegible]