

2016 Toyota 86 2.0GT		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-ZN6	DISPLACEMENT 1,998 cc		
YEAR / REG. 2016/10	MILEAGE 107,000 km		
DOORS 2	SEATS 4		
DRIVETRAIN 2WD (FR)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Coupe		
CHASSIS NO. ZN6-070339	DIMENSIONS (L X W X H) 424 × 178 × 132 cm		
SALES POINTS			
Alloy Wheels Navigation System		Cruise Control	
INSPECTOR REPORT			
Core support replaced, left and right front side members distorted, left front instrument panel tip distorted, dashboard panel lifted, steering wheel and seat scuffs.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H28 10月	メーカー トヨタ	ドア枚数 2	ボディ形状 クーペ	評価点 R
車名 86	グレード 2.0 GT TRDフルエアロ TRDマフラー BLITZ車高調	駆動方式 2WD 4WD	車種区分	
車種 自動車・その他 ()	排気量 2000 cc	型式 DBA-ZN6	登録 A・B・C	
車検 9年7月	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書等)	
走行 107,000 km	フロア 6 MT			
外装色 クリスタルホワイトパール	カラーNo. Qd・AAG・WAG・ ()	エアコン	新車品のみ O印 を記入	
内装色 ()	乗車定員 4人	サンルーフ	高シート	
小計 左・右 ディーラー・走行	9,320円	エアロ	ナビ	スズ
セールスポイント				
キーレスエントリー/ABS/運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/フルセグTV/ETC/スマートキー/フルエアロ/ローダウン/盗難防止システム/オートクルーズコントロール/LEDヘッドライト/横滑り防止装置 (ESC)/DVD再生/CD/バックカメラ				
検査記入欄				
コアサポート交換 左右フロントサイドメンバーひずみ 左フロントインパネ先ひずみ ダッシュ板浮き ハンドルシートスレ				
修理歴 G・無				
A キズ U ヘコみ/サレ B キズ/ヘコみ P 色あせ/ボケ Q ガラスキズ W 腐蝕品 S サビ C 腐食 X 交換品 XX 交換済				
登録No. 月 日 までには名義できる方				
車体番号 ZN6-070339				
FW トボ石 傷A フレ 外装 小 ホイル エアロ A・U A・曲 A・フレ	シリアル No.			
内装 3ゴレ シミ ヤブレ コゲ コガ穴 オーディオ穴 スレ	長さ cm	幅 cm	高さ cm	最大積載量 kg