

2016 Toyota Passo Passo 1.0 Moda S		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-M700A	DISPLACEMENT 996 cc		
YEAR / REG. 2016/06	MILEAGE 27,974 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Hatchback		
CHASSIS NO. M700A-0011290	DIMENSIONS (L X W X H) 366 × 166 × 152 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Exterior has minor scratches and dents. Interior trim has scratches. Windshield has scratches, stone chips, cracks, and repair marks, requiring replacement. Interior also shows scratches, dirt, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録年月 平成28年 6月	車名・グレード ハッソ モータS	2WD 4WD	評価点 (5)		
ディーラー・並行 モビル年式 年	型式 DBA-M700A	排気量 1000 CC	ドア 5 形状 木		
ハンドル 左・右		定員 5人 積載 kg	外装 内装 A A		
車種 自家用	シフト CAT	セールスポイント (正常に機能するものに限ります)			
車検 令和9年 6月 (日)	冷暖房 AAC	スマートキー・ETC			
走行 2万7千917 km	燃料 ガソリン	ワンオーナー バックカメラ フォグランプ			
色 レッド	色コード R72/FB10	装備品 (純正品に限り○をつけてください)			
R券 8,190 円		(PS) (PW) (BS) (TB) (AW) SR ナビ TV カフ			
注意事項申告欄		新車保証書 有・無			
外装 小A・小U					
ルームトリムキズ					
フロントガラス	キズ・飛石・ヒビ割・リペア跡・X要	A-キズ E-エクボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済			
内装	キズ・汚レ・コゲ・穴・スレ・キレ・破レ	型式指定番号 18322			
車台番号	0011290	車検区分番号 0004			
登録番号	名変中	車検有効期 366 日			
		長さ 166 高さ 152			