


2016 Toyota Passo X L Package S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-M700A	DISPLACEMENT 996 cc		
YEAR / REG. 2016/05	MILEAGE 12,720 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Hatchback		
CHASSIS NO. M700A-0005048	DIMENSIONS (L X W X H) 365 × 167 × 153 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
W cover A, various scratches, dents, and light scratches A.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H28 5月		メーカー トヨタ		ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4																				
車名 パッソ		グレード X LパッケージS		駆動方式 4WD																						
車種 自家用・その他 ()	排気量 1000 cc	型式 DBA-M700A	通称 型式	内装 A・⑨・C																						
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書 等)																							
走行 12,720 km	シフト インパネ	AT																								
外装色 レッド	カラーNo. (R67)	エアコン	新着品のみ ○印 を記入																							
内装色 ()	乗車定員 5 人	AW	サンルーフ	革シート																						
左・右 左・右	輸入 区分	ディーラー	並行	ナシ	8,190 円	・ 預託金																				
セールスポイント スマートキー・プッシュスタート・スマートアシスト II・エコアイドル・ナビ・TV・バックカメラ・ETC																										
検査記入欄 WカバーA 各キズ、U、ウスA			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
登録No. M700A-0005048			名義中 月 日 までに名義できる方																							
シリアル No.			車検 有効																							
FW ⑨	備A	ワレ	外装 ⑨・⑩	小 ⑨・⑩	エアロ A・ワレ	シリアル No.																				
内装 ⑨	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	最大積載量 kg																				