

2017 Audi Audi A3 Sedan 1.4 TFSI Sport		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-8VCXSL	DISPLACEMENT 1,394 cc		
YEAR / REG. 2017/06	MILEAGE 59,511 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. WAUZZZ8V2H1032372	DIMENSIONS (L X W X H) 447 × 180 × 139 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Interior: Steering wheel wear, seat wear, trim A. Exterior: Minor thin scratches. Front windshield: Stone chip. Interior: Dirt, scuffs.			

ORIGINAL JAPANESE AUCTION SHEET

年式車種 H29 / 6月	メーカー アウディ	ドア数 4	ボディ形状 セダン	評価点 4.5
車名 A3セダン	グレード 1.4 TFSI スポーツ	駆動方式 4WD	燃費区分 4WD	
車種 自家用・その他 ()	排気量 1390 cc	型式 DBA-8VCXSL	通称 A・B・C	
年式 8年	月 6月	燃料 ガソリン	ディーゼル ハイブリッド ()	後付部品 () 車・取付説明書 ()
走行 59,511 km	シフト AT	エンジン AG・AGD・WAG ()	新車のみ O印 を記入	
外装色 イエロー	カラーNo. (LZ1A)	内装色 その他	乗車定員 5人	PS () ABS () ナビ () TV () キーレス ()
走行 左・右・前・後・走行	15,160円	リサイクル料	エコマーク	
セールスポイント				
0				
検査記入欄				
内装 ハンドルスレ シートスレ トリムA				
外装 傷痕A				
修復歴 有 ()				
A B C D E F G H I J K L M N O P Q R S T U V W X Y Z				
W 補修部 S サビ C 腐食 X 交換部 XX 交換済				
登録No. 月 日 までには名実できる方				
名実中				
登録番号 WAUZZZ8V2H1032372				
シリアル No.				
重量 全重 最高 最低 最大積載量 0 kg				