

2017 BMW 1 SERIES 118d M Sport		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
LDA-1S20	1,995 cc		
YEAR / REG.	MILEAGE		
2017/04	23,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBA1S52070V843198	434 × 177 × 143 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Cruise Control		Navigation System	
INSPECTOR REPORT			
If there were any noticeable scratches or dents on the exterior, they have been neatly repaired, but small scratches or dents may still remain. There are some noticeable stains on the interior, but only in certain areas. No repair history or abnormalities in the structural components.			

新年度登録 H29 4月		メーカー BMW		グレード 5		型式・部位 コンパクトハッチバック		評価点 5	
車名 1 シリーズ		ドア数 1 1 8 d		Mスポーツ Mスポーツ		型式 ディーゼル		型式 A	
車種 自家用		ディーラー 右		型式 LDA-1520		年式 2000		型式 ディーゼル	
年式 10年		月 4月		抹消 抹消		年式 10年		月 4月	
外装色 ホワイト		カラーNo. 300		リサイクル料 18,570円		車体番号 WBA1S 52070R43198		型式 AAC	
シフト フロア		AT AT		乗車定員 5人		長さ cm		幅 cm	
走行回り送 ()		車検 車検		車検 車検		車検 車検		車検 車検	
車検 車検		車検 車検		車検 車検		車検 車検		車検 車検	
車検 車検		車検 車検		車検 車検		車検 車検		車検 車検	
車検 車検		車検 車検		車検 車検		車検 車検		車検 車検	
車検 車検		車検 車検		車検 車検		車検 車検		車検 車検	
車検 車検		車検 車検		車検 車検		車検 車検		車検 車検	
車検 車検		車検 車検		車検 車検		車検 車検			