

2017 BMW 1 SERIES 118d Style		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-1S20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2017/08	MILEAGE 36,059 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. WBA1S52090V844918	DIMENSIONS (L X W X H) 434 × 177 × 144 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Navigation System		Leather Seats (Cloth & Leather) Cruise Control	
INSPECTOR REPORT			
Minor scuffs on driver's seat, door trim, and steering wheel. Repair marks on the right quarter panel.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29/8月	メーカー BMW	ドア枚数 5	ボディ形状 コンパクトハッチバック	評価点 4.5
車名 1シリーズ	グレード 118dスタイル	駆動方式 4WD	4WD	
車歴 自用・その他()	排気量 2000 cc	型式 LDA-1S20	通称 A・C	
車検 8年9月/抹消	燃料 ガソリン	デジ ハイブリッド	後日選り込み 保証書・取付品等	
走行 36,059 km	フロア AT	手帳		
外装色 Pホワイト	カラーNo. QD・AAG・WAG・()	装備品のみ O印を記入		
内装色 ()	乗車定員 5人	PS PW A サンルーフ 革シート		
左・前 左・前 左・前	走行 18,570 km	エレクト A A TV A		
セールスポイント Bカメラ、ETC、マット、スマートK				
検査記入欄 運転席すれ<小>、ドア内張りすれ<小>、ハンドルすれ<小>、右クォタ修理跡、				
修復歴 有・C				
A ネズ U ヘコ ネズ P 色あ Q ガラス W 破損 S サビ C 腐食 X 交換 XX 交換				
名 月 日 まで WBA1S52090V844918				
車体 No.				
A ネズ U ヘコ ネズ P 色あ Q ガラス W 破損 S サビ C 腐食 X 交換 XX 交換				
A ネズ U ヘコ ネズ P 色あ Q ガラス W 破損 S サビ C 腐食 X 交換 XX 交換				