


2017 BMW 1series 118i Style		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
1R15	1,498 cc		
YEAR / REG.	MILEAGE		
2017/02	82,618 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Orange	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBA1R52040V876963	434 × 177 × 144 cm		
SALES POINTS			
Alloy Wheels		Leather Seats (Cloth & Leather)	
Pre-Collision Braking		Cruise Control	
Navigation System			
INSPECTOR REPORT			
Left mirror scratch			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29/2月	メーカー BMW	ドア数 5	ボディ形状 コンパクトハッチバック	評価点 4
車名 1シリーズ	グレード 118iスタイル	駆動区分 2WD	4WD	
車種 自家用・その他 ()	排気量 1500 cc	型式 1R15	変換形式	内装 A・⑤・C
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	後日選り込み (保証書・取扱説明書 等)	
走行 82,618 km	シフト フロア 8 AT			
外装色 オレンジ	カラーNo. ()	④D・AAG・WAG・()	新着品のみ O印 を記入	
内装色 ()	乗車定員 5 人	⑤	⑥	⑦ サンルーフ ⑧ 革シート
⑨ 左・⑩ 右 ⑪ 輸入 ⑫ 国産	⑬ 走行 ⑭ 18,570 km	⑮ ⑯ ⑰ ⑱	⑲ TV	⑳ ス
セールスポイント CD/バックカメラ/運転席エアバック/盗難防止システム/ スマートキー/キーレスエントリー/ABS/助手席エア バック/サイドエアバック/HDDナビ				
				
修復歴 有・⑮				
検査記入欄 左ミラーきず				
A キズ U ヘッドランプ B キズ・ヘッド P 熱気センサー Q ガラスキズ W 経年劣化 S サイズ C 腐食 X 交換済 YX 交換済 登録No. 月 日 まで(名義できる方) 車体番号 WBA1R52040V876963 シリアルNo. ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳				
① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳	① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳			