

2017 BMW BMW X3 Blackout		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-WY20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2017/02	MILEAGE 49,284 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. WBAWY320400V61672	DIMENSIONS (L X W X H) 466 × 190 × 168 cm		
SALES POINTS			
Alloy Wheels Roof Rails Power Tailgate Pre-Collision Braking Front Camera Back Camera HiFi Speaker System (205W, 9 speakers)		Sunroof Leather Seats (Leather) Power Seats (Front) Adaptive Cruise Control Side Camera Navigation System	
INSPECTOR REPORT			
Studless tires. Driver's seat has wrinkles and a tear. Steering wheel shows scuffs. Underbody has paint damage and rust. Right front bumper cover is detached and has a hole.			

ORIGINAL JAPANESE AUCTION SHEET

H29 / 2月		BMW		5	SUV/クロカン	4.5
X 3		ブラックアウト		2WD	4WD	
車種	白身用 ・ その他 ()	排気量	2000 cc	型式	LDA-WY20	内装
車検	- - 年 / 月 / 日	燃料	ガソリン	駆動方式	2WD	A ・ ⑤ ・ C
走行	49,284 km	フロア	AT	スペアキー、BMWディーラー2年点検記録簿有、etc		
外装色	ブラック (475)	エアコン	AG ・ ⑤ ・ WAG ・ ()	新車品のみ、O印 を記入		
内装色	()	乗車定員	5 人	⑤	⑥	⑦
左・前・後・右	⑤	⑥	⑦	⑧	⑨	⑩
⑪	⑫	⑬	⑭	⑮	⑯	⑰
セールスポイント ミラーETC、純ナビ、フルセグTV、F・Rカメラ、サンルーフ、黒レザーシート、パワーバックドア、F・Rシートヒーター、ヘッドアップディスプレイ、アダプティブLEDヘッドライト、夏タイヤ (純19AW付) 精込、純フロアマット&ドアバイザー、走行中TVOK、インテリジェントセーフティ、限定車、スタッドレスAW付装着						
検査記入欄 スタッドレスT、Dシートシワ・切れ、ハンドルスレ、下廻りペイント・サビ、右Fバンパーカバー外れ・穴						
車検番号 WBAWY320400V61672						
⑱	⑲	⑳	㉑	㉒	㉓	㉔
⑳	㉑	㉒	㉓	㉔	㉕	㉖
㉗	㉘	㉙	㉚	㉛	㉜	㉝
㉞	㉟	㊱	㊲	㊳	㊴	㊵