

2017 BMW BMW X5 xDrive 35d M Sport Select PKG		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
LDA-KS30	2,992 cc		
YEAR / REG.	MILEAGE		
2017/07	52,747 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBAKS420900J70300	491 × 199 × 176 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Roof Rails		Leather Seats	
Power Tailgate		Power Seats (Front)	
Pre-Collision Braking		Adaptive Cruise Control	
Front Camera		Side Camera	
Back Camera		Navigation System	
HiFi Speaker System (205W, 9 speakers)			
INSPECTOR REPORT			
Light interior dirt			

年式/月 H29 / 7 月		メーカー BMW		ドア数 5		試運転可能 SUV/クローン		評価点 4.5	
車種 自家用・その他 ()		排気量 3000		型式 CC		型式 LDA-KS30		別装 A・B・C	
車検 - 年 - 月 - 日		燃料 ガソリン		モーター ハイブリッド		後付選り付け品 (② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫)			
走行 10000 km		シート フロア		AT					
外装色 パール		カラーNo. AD・AG・WAG・()		エンジン 5		新着品のみ O印を記入			
()		内装色 5		乗車人数 5		① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫			
左・交・変 ④		輸入 ④		走行 25,460		① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫			
セールスポイント									
★ワンオーナー★セレクトPKG★パノラマサンルーフ ★本革シート (モカ) ★シートヒーター X4 ★LED ★ヘッドライト★アクティブクルーズコントロール★オブ ション2インチAW★社外足回り★パワーバックドア ★純正ナビ・TV★全方向カメラ★PDCモニター★フォ トアクセス★ミラーETC★インテリジェントセーフ ティ★									
検査記入欄									
ルーフ内汚汚れ									
検査履歴 有、 ⑥									
A1 									
W 補修 B 事故 C サビ D 変換 E 交換 F 交換 G 交換 H 交換 I 交換 J 交換 K 交換 L 交換 M 交換 N 交換 O 交換 P 交換 Q 交換 R 交換 S 交換 T 交換 U 交換 V 交換 W 交換 X 交換 Y 交換 Z 交換									
月 日 家で名義変更する									
車検 WBAKS 420900J 70300									
シリアル No.									
最大積載量									