

2017 BMW BMW2seriesGranTourer 218d Gran Tourer Luxury		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE LDA-2E20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2017/06	MILEAGE 43,786 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. WBA2E520305G91872	DIMENSIONS (L X W X H) 457 × 180 × 165 cm		
SALES POINTS			
Alloy Wheels Leather Seats (Perforated Dakota Leath... Back Camera		Power Seats (Front) Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Steering wheel wear, seat wrinkles/wear/dirt, trim minor scratches, headliner wear, exterior light scratches, exterior chrome fading, aluminum wheel minor scratches.			

ORIGINAL JAPANESE AUCTION SHEET

年式車種 H29 / 6月	メーカー BMW	ドア数 5	ボディ形状 セダン	評価点 4.5
グレード 2 シリーズ	218d グランツァー ラーラゲジュアリー	駆動方式 4WD	4WD	
車種 自家用・その他 ()	排気量 1990 cc	型式 LDA-2E20	通称 A・B・C	内装 A・B・C
車検 8年6月 / 抹消	燃料 ガソリン ハイブリッド ()	シフト AT	後部座席 ()	装備品 ()
走行 43,786 km	カラーNo. ホワイト (300)	エンジン AG・AGD・WAG ()	装備品のみ O印 を記入	
外装色 ()	内装色 その他	乗車定員 7人	PS ()	サンルーフ ()
走行 左・右・前・後 20,710 km	走行 20,710 km	エアロ エディック	ABS ()	キーレス ()
セールスポイント				
シートヒーター メモリー付きパワーシート HUD				
検査記入欄				
ヘッドランプ シートベルト、スレ、汚れ トリム 天幕スレ				
外装ウレ 外装メッキ部アセ アルミホイールガリ				
修理歴 有・無				
A キズ B ヘッドランプ C キズ・ヘッ D キズ・ヘッ E 色あせ・ボケ F ガラスキズ W 経年劣化 S サビ C 腐食 X 交換済 XX 交換済				
名義中				
月 日 までに見学できる方				
WBA2E520305G91872				
最大積載量 0 kg				